

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011702/UPA3Q2**Date:** 19/05/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000537

Claimant Vehicle No : SLV3720C **Insured Vehicle No :** YP1116M

Date of Loss: 16/11/2022 Nature of Claim: TP Claim No: SVRAISCL2022-00070

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV3720C**
 Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB5959976
 Reg. Date: 28/12/2017 (Man. Year: 2017) Chassis No: RU31259959
 Colour: Red Odometer: 60908 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,895.70	1,160.96	4,734.74	80.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	950.00	1,750.00	64.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,595.70	2,110.96	6,484.74	75.44
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	8,595.70	1,650.00	6,945.70	80.80
+ GST 8.00/8.00% (S\$)	687.66	132.00	555.66	80.80
Nett Amount (S\$)	9,283.36	1,782.00	7,501.36	80.80
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Car Rental (2.0 x S\$100.00/day + 8.00% GST) (S\$)		216.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,065.45		
Global Sum Settlement (S\$)		2,060.00		

INSPECTION

Date of Assignment: 22/11/2022

Date Inspected: 07/12/2022 Inspected At:

Abwin Service Pte Ltd (HQ)
 17 Kaki Bukit Road 4, Bartley Biz Centre #01-
 58/59/60/61/62
 Singapore 417809

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV3720C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	972.20 F	*- FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	38.20 F	*- FL
3	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	35.80 F	*- FL
4	1		*FRONT FENDER LH	Dented	449.70 F	*449.70 FL
5	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	151.50 F	*- FL
6	1		*FRONT WHEEL ARCH GARNISH LH	Cut	140.90 F	*140.90 FL
7	1		*HEADLAMP LH	Not Necessary	1,999.40 F	*- FL
8	1		*HEADLAMP BRACKET LH	Not Necessary	55.60 F	*- FL
9	1		*FRONT LH DOOR	Repair	889.00 F	*- FL
10	1		*FRONT LH DOOR HINGE UPPER	Not Necessary	51.40 F	*- FL
11	1		*FRONT LH DOOR HINGE LOWER	Not Necessary	51.40 F	*- FL
12	1		*SIDE MIRROR HOUSING LH	Damaged	650.50 F	*650.50 FL
13	1		*SIDE MIRROR COVER LH	Missing	210.10 F	*210.10 FL
14	10		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
15	10		*FENDER INNERSHIELD CLIPS	Not Necessary	50.00 FS	*- FS
16	10		*HEADLAMP CLIPS	Not Necessary	50.00 FS	*- FS
17	10		*DOOR CLIPS	Not Necessary	50.00 FS	*- FS
					Sub Total (\$\$)	5,895.70 1,451.20
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 290.24
					Total Parts (\$\$)	5,895.70 1,160.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED PARTS	New	1,200.00	300.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	600.00
3	TO APPLY UNDERCOATING FOR RUST PROOFING	New	180.00	30.00
4	TO CHECK WIRING	New	120.00	20.00
Gross Labour Cost (\$\$)			2,700.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >