

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

ABWIN
 Service Pte Ltd

M9 Automobile Pte Ltd
M9 International Pte Ltd

ESTIMATED COST: HQQ000698

TO : ALLIANZ INSURANCE SINGAPORE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SLV3720C
JEN WEI ZUN
 BLK 409B
 FERNVALE ROAD
 #21-60
 SINGAPORE,
 SINGAPORE 792409
 CONTACT NO : 91691234

DATE : 03-DEC-2022
 MAKE : HONDA
 MODEL : VEZEL HYBRID 1.5X AUTO
 CHASSIS NO : RU31259959
 ENGINE NO : LEB5959976
 SERVICE ADVISOR : HAZEL
 PAGE : 1 OF 2

Not Allowed
noisy her
2/5 # 1650
7/12/22
take photo after rep- 3 days

QTY DESCRIPTION 90096608 REPAIR AMOUNT (SGD) SURVEYOR APP (SGD)

LIST ITEM

1	FRONT BUMPER	~	972.20	X
1	FRONT BUMPER SIDE RETAINER LH	11	38.20	X
1	FRONT BUMPER SIDE BRACKET LH	11	35.80	X
1	FRONT FENDER LH	20	449.70	—
1	FRONT FENDER INNER SHIELD LH	11	151.50	X
1	FRONT WHEEL ARCH GARNISH LH	(11)	140.90	—
1	HEADLAMP LH	11	1,999.40	X
1	HEADLAMP BRACKET LH	11	55.60	X
1	FRONT LH DOOR	2	889.00	X
1	FRONT LH DOOR HINGE UPPER	11	51.40	X
1	FRONT LH DOOR HINGE LOWER	11	51.40	X
1	SIDE MIRROR HOUSING LH	242	650.50	—
1	SIDE MIRROR COVER LH	m.s	210.10	—
Sub Total			5,695.70	0.00

SPECIAL NETT

10	FRONT BUMPER CLIPS	11	50.00	X
10	FENDER INNERSHIELD CLIPS	11	50.00	X
10	HEADLAMP CLIPS	11	50.00	X
10	DOOR CLIPS	11	50.00	X
Sub Total			200.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,200.00	300	
1	TO SPRAY PAINT ON AFFECTED AREAS	1,200.00	600	
1	TO APPLY UNDERCOATING FOR RUST PROOFING	180.00	30	
1	TO CHECK WIRING	120.00	20	

P-1451.2
202
1160.96
950
2110.96