

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/A1522011702/upa3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / VMS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐
☐

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐
☐
☐
☐

: Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ESTIMATED COST: HQQ000698

TO : ALLIANZ INSURANCE SINGAPORE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SLV3720C
JEN WEI ZUN
 BLK 409B
 FERNVALE ROAD
 #21-60
 SINGAPORE,
 SINGAPORE 792409
 CONTACT NO : 91691234

Signature: _____
 DATE : 03-DEC-2022
 MAKE : HONDA
 MODEL : VEZEL HYBRID 1.5X AUTO
 CHASSIS NO : RU31259959
 ENGINE NO : LEB5959976
 SERVICE ADVISOR : HAZEL
 PAGE : 1 OF 2

*Not Allowed
 Noisy here
 2/5 #1650
 7/12/22
 take photo after rep- 3 days*

QTY DESCRIPTION REPAIR AMOUNT (SGD) SURVEYOR APP (SGD)

LIST ITEM

1	FRONT BUMPER	~ 972.20	X
1	FRONT BUMPER SIDE RETAINER LH	11 38.20	X
1	FRONT BUMPER SIDE BRACKET LH	11 35.80	X
1	FRONT FENDER LH	20 449.70	—
1	FRONT FENDER INNER SHIELD LH	11 151.50	X
1	FRONT WHEEL ARCH GARNISH LH	(11) 140.90	—
1	HEADLAMP LH	11 1,999.40	X
1	HEADLAMP BRACKET LH	11 55.60	X
1	FRONT LH DOOR	2 889.00	X
1	FRONT LH DOOR HINGE UPPER	11 51.40	X
1	FRONT LH DOOR HINGE LOWER	11 51.40	X
1	SIDE MIRROR HOUSING LH	242 650.50	—
1	SIDE MIRROR COVER LH	m.s 210.10	—
Sub Total		5,695.70	0.00

SPECIAL NETT

10	FRONT BUMPER CLIPS	11 50.00	X
10	FENDER INNERSHIELD CLIPS	11 50.00	X
10	HEADLAMP CLIPS	11 50.00	X
10	DOOR CLIPS	11 50.00	X
Sub Total		200.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,200.00	300
1	TO SPRAY PAINT ON AFFECTED AREAS	1,200.00	600
1	TO APPLY UNDERCOATING FOR RUST PROOFING	180.00	30
1	TO CHECK WIRING	120.00	20

*1451.2
 202
 1160.96
 950
 2110.86*