

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM22011705/UP3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Veh No:

GBL7870Y

Yr Regn:

09/09/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

NISSAN NV200 c.c 1598

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

15840

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1YAA2020001811

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

165/80R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

21/11/22

D.O.I.

22/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rear wlscreens shattered

The U/C / Chassis frame / Body Structure affected due to collision.

2/12/22 P/P #7435-SV in hand MA see

HSIAO Tony

not Arthur
22/11/22
P/P \$7435.50
4 days.

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Tklee0247@gmail.com

Vehicle Number: GBL7870Y

Vehicle Model: NISSAN NV 200

PAGE 1

PARTICULAR	AMOUNT
QTY <i>nett item</i>	SS

LIST PRICE

1	1	REAR TAILGATE	<i>body 2D</i>	\$	1,978.40	
2	1	REAR TAILGATE GLASS	<i>shotted</i>	\$	1,320.50	
3	1	REAR TAILGATE VIEW MIRROR	<i>n1</i>	\$	431.60	X
4	1	REAR TAILGATE WIPER ARM	<i>cur</i>	\$	110.20	
5	1	REAR TAILGATE WIPER MOTOR	<i>butlyn</i>	\$	581.90	
6	1	REAR TAILGATE LOGO	<i>ner</i>	\$	79.90	
7	1	REAR TAILGATE EMBLEM "NV200"	<i>ner</i>	\$	145.20	
8	1	REAR TAILGATE EMBLEM "VANETTE"	<i>ner</i>	\$	68.60	
9	1	REAR TAILGATE OUTER GARNISH	<i>gross</i>	\$	351.50	
10	1	REAR TAILGATE INNER LOCK	<i>gm</i>	\$	260.60	
11	1	REAR TAILGATE INNER LOCK ACTUATOR	<i>n1</i>	\$	281.20	X
12	1	REAR TAILGATE INNER TRIM	<i>twi/trim</i>	\$	286.90	
13	1	REAR TAILGATE WEATHER STRIP	<i>tm</i>	\$	241.20	
14	2	REAR TAILGATE HINGE - RH/LH @68.50	<i>n1</i>	\$	137.00	X
15	2	REAR TAILGATE DAMPER - RH/LH @195.60	<i>n1</i>	\$	391.20	X
16	2	REAR TAILGATE SIDE STOPPER - RH/LH @48.20	<i>n1</i>	\$	96.40	X
17	2	REAR TAILLAMP - RH/LH @283.20	<i>o/s cre</i>	\$	566.40	<i>irc</i>
18	1	REAR TAILLAMP FILLER PANEL -RH	<i>n</i>	\$	425.00	X
19	1	REAR BUMPER	<i>22/22</i>	\$	632.70	
20	1	REAR BUMPER SPONGE	<i>toin</i>	\$	194.70	
21	2	REAR BUMPER SIDE RETAINER - RH/LH @ 42.90	<i>n1</i>	\$	85.80	X
22	1	REAR END PANEL	<i>n</i>	\$	411.50	X
23	1	REAR END PANEL TOP GARNISH	<i>n1</i>	\$	128.60	X
				\$	9,207.00	
				LESS 10%	\$	920.70
					\$	8,286.30

SPECIAL NETT ITEMS

1	1	(SET) REAR TAILGATE GLASS SEALANT	<i>ner</i>	\$	80.00	40
2	1	(SET) REAR TAILGATE GLASS FOAM TAPE	<i>ner</i>	\$	60.00	30
3	1	(SET) REAR <i>licence plate</i>	<i>but</i>	\$	60.00	40
4	1	(SET) REAR BUMPER CLIP	<i>ner</i>	\$	45.00	30
5	1	(SET) REAR REVERSE SENSOR	<i>shotted</i>	\$	280.00	200
6	1	REAR TAILGATE STICKER "70KM"	<i>ner</i>	\$	10.00	✓
7	1	REAR TAILGATE STICKER "8PAX"	<i>ner</i>	\$	10.00	✓
8	1	REAR TAILGATE RECORDER CAMERA	<i>ner</i>	\$	550.00	X
9	1	REAR TAILGATE <i>solar film</i>	<i>ner</i>	\$	350.00	180
				\$	1,445.00	

T K LEE AUTOMOTIVE PTE.LTD

PAGE 2

Vehicle Number: GBL7870Y

Vehicle Model: NISSAN NV 200

LABOUR CHARGES

1	TO REMOVE & REPLACE TAILGATE GLASS	\$	180.00	100
2	TO TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	\$	150.00	60
3	TO CHECK REAR ELECTRICAL WIRING	\$	50.00	20
4	TO REMOVE AND REPLACE REAR REVERSE SENSOR AND CAMERAS	\$	100.00	50
5	TO TUFF KOTE	\$	80.00	40
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$	1,080.00	500
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$	1,000.00	550
8	TO VACUUM, WAXING AND CLEANING INTERIOR TRIMS	\$	11 150.00	X
		\$	2,790.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 12,521.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6195
102
8575.5
540
1320
7435.50