

ASS. REC. BY:

REF:

AUG 1 22 011710 / KCP

Kennerth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1. B. /

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S140 97934

Yr Regn:

12, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. White 1Pr

A/C:

Insured / Std / NI / NA

Sp. Reading

145559

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKCB31F4203093195

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F: Wanli

195/65R15

R: Pailun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

17/4/22

Rear

R/Bal.

7

mm

L/Bal.

7

mm

D.O.I.

18/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/4

81771.23

Cabs

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9793U

Not Authorized
Permy B4 paint
1771.23

AAD2211-075

Vehicle No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 NOV 2022**SHD9793U**

200303878K

TOYOTA

PRIUS **GEN 4**

17/11/2022

SMC8007J/AIG

11/12/2020

PART**LIST**

1	COVER, REAR BUMPER	\$	<i>Bulom</i> 485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>B4</i> 332.70	✓
1	COVER, REAR BUMPER, LOWER	\$	<i>nu</i> 22.00	✓
1	GUARD, REAR BUMPER, CENTER	\$	<i>cm</i> 374.50	✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>DIY</i> 132.60	✓
1	REFLECTOR ASSY, REFLEX, RH	\$	<i>cm</i> 39.00	✓
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$	<i>sn</i> 339.60	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$	<i>sn</i> 261.00	X
1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>sn</i> 100.40	X
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>R</i> 1,147.80	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>na</i> 54.60	X
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>na</i> 54.60	X
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>na</i> 47.90	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>sn</i> 913.60	X
1	WEATHERSTRIP, BACK DOOR	\$	<i>sn</i> 372.30	X
1	PAN, REAR FLOOR	\$	<i>R</i> 583.40	X
1	COVER, FLOOR UNDER, NO.1 LH	\$	<i>sn</i> 175.10	X
1	COVER, FLOOR UNDER, NO.2 RH	\$	<i>DIY</i> 241.90	✓
1	COVER, REAR FLOOR CTR	\$	<i>sn</i> 229.90	X
1	COVER, DECK TRIM, REAR	\$	<i>sn</i> 126.70	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 651.00	X
1	STAY ASSY, BACK DOOR, LH	\$	<i>sn</i> 242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	<i>sn</i> 242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	<i>R</i> 61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>R</i> 61.00	X

Trans-cab Auto Services Pte Ltd

AAD2211-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9793U

TOTAL	\$	7,293.20
25%	\$	1,823.30
	\$	5,469.90

Special Nett

1SET PARKING AID	\$	<i>Sm</i> 700.00	<i>X</i>
1SET REAR BUMPER CLIP	\$	<i>na</i> 95.00	<i>60na</i>
2 WINDSCREEN SEALANT	\$	<i>na</i> 150.00	} <i>X</i>
1 WINDSCREEN MOULDING	\$	<i>na</i> 200.00	
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 130.00	
1 REAR TAILGATE STICKER "Trans-Cab"	\$	<i>na</i> 80.00	
1 REAR TAILGATE STICKER "6555-3333"	\$	<i>na</i> 80.00	
1 REAR BUMPER PROTECTOR	\$	<i>na</i> 180.00	}
1SET REAR BUMPER RETAINER CLIP	\$	<i>na</i> 85.00	
1 END PANEL TRIM CLIP	\$	<i>na</i> 65.00	

TOTAL	\$	1,765.00
--------------	-----------	-----------------

TOTAL PARTS	\$	7,234.90
--------------------	-----------	-----------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 300.00	<i>X</i>
--	----	------------------	----------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
---	----	------------------	----------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,400.00	<i>2001</i>
---	----	----------	-------------

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
--	----	------------------	----------

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i> 180.00	<i>X</i>
---	----	------------------	----------

Trans-cab Auto Services Pte Ltd

AAD2211-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9793U

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 250.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,400.00	<i>2201</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
To remove and replace corporate sticker	\$	<i>nn</i> 250.00	<i>X</i>

TOTAL \$ 5,260.00**Over All Total \$ 12,494.90****(PART-BY-PART) Repair Days*****7 DAYS******2 day!*****LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD9793U
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2H36887
Chassis No.:	JTDKB3FU203093195
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	11 Dec 2020
First Registration Date:	11 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2028
PARF Rebate Amount:	\$10,897.00

Intended COE Rebate Details

COE Expiry Date:	10 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$29,843.00
COE Rebate Amount:	\$22,606.00
Total Rebate Amount:	\$33,503.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Nov 2022

OK