

Premium Carz Services Pte Ltd

Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 21-11-22

Xiao Tony

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA TOWER
Singapore 068811

Our Customer : Chng Yai Wun

Vehicle No : SGJ6748B

Model : Nissan Latio 1.5L T

Manufacture Year : 2006

Date of Accident : 21-11-22

Total Estimate Repair Days : 12

Total Pages : 2

Attn : Motor Claims Department
Tel: 6880 4741

JN1BAAC1120001212

Re: Repair Estimate For Third Party Claim against SGG4930U

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front Bumper <i>Replaced</i>	1	\$572.20	572.20	<i>✓</i>
2	Front Bumper bracket RH <i>Replaced</i>	1	\$91.70	91.70	<i>✓</i>
3	Front bumper bracket LH <i>Replaced</i>	1	\$91.70	91.70	<i>✓</i>
4	Front RH Fender <i>Replaced</i>	1	\$786.80	786.80	<i>✓</i>
5	Front LH signal lamp <i>Replaced</i>	1	\$71.40	71.40	<i>✓</i>
6	Front LH Door <i>Replaced</i>	1	\$1,274.90	1,274.90	<i>✓</i>
7	Front LH door lock <i>Replaced</i>	1	\$259.00	259.00	<i>✓</i>
8	Front LH door center pillar <i>Replaced</i>	1	\$2,169.80	2,169.80	<i>✓</i>
9	Front LH door <i>Replaced</i>	1	\$1,274.90	1,274.90	<i>✓</i>
10	Front LH door power window motor <i>Replaced</i>	1	\$742.40	742.40	<i>✓</i>
11	Front LH door p/w motor regulator <i>Replaced</i>	1	\$114.40	114.40	<i>✓</i>
12	Front LH door p/w motor regulator <i>Replaced</i>	1	\$110.50	110.50	<i>✓</i>
13	Front LH weatherstrip <i>Replaced</i>	1	\$1,274.90	1,274.90	<i>✓</i>
14	Rear LH door <i>Replaced</i>	1	\$613.60	613.60	<i>✓</i>
15	Rear LH door power window motor <i>Replaced</i>	1	\$114.40	114.40	<i>✓</i>
16	Rear LH door p/w motor regulator <i>Replaced</i>	1	\$114.40	114.40	<i>✓</i>
17	Door hinge LH - Frt & Rear <i>Replaced</i>	2	\$68.50	137.00	<i>✓</i>
18	Rear LH weatherstrip <i>Replaced</i>	1	\$110.50	110.50	<i>✓</i>
19	Front wheel bearing LH <i>Replaced</i>	1	\$333.50	333.50	<i>✓</i>
20	Front wheel bearing RH <i>Replaced</i>	1	\$333.50	333.50	<i>✓</i>
21	Rear fender LH <i>Replaced</i>	1	\$1,256.40	1,256.40	<i>✓</i>
22	RH side skirt <i>Replaced</i>	1	\$1,176.60	1,176.60	<i>✓</i>
23	LH side skirt <i>Replaced</i>	1	\$1,176.60	1,176.60	<i>✓</i>
24	LH rear wheel hub bearing <i>Replaced</i>	1	\$374.00	374.00	<i>✓</i>
25	Engine lower cover <i>Replaced</i>	1	\$107.00	107.00	<i>✓</i>
26	Engine lower cover <i>Replaced</i>	1	\$107.00	107.00	<i>✓</i>
27	Rear fender inner shield RH <i>Replaced</i>	1	\$317.00	317.00	<i>✓</i>
28	Rear fender inner shield LH <i>Replaced</i>	1	\$317.00	317.00	<i>✓</i>
29	Rear fender LH <i>Replaced</i>	1	\$1,256.40	1,256.40	<i>✓</i>
30	Front door outer moulding LH <i>Replaced</i>	1	\$157.80	157.80	<i>✓</i>
31	Front door handle LH <i>Replaced</i>	1	\$134.00	134.00	<i>✓</i>
32	Rear door handle LH <i>Replaced</i>	1	\$134.00	134.00	<i>✓</i>
33	Rear door trimboard LH <i>Replaced</i>	1	\$984.10	984.10	<i>✓</i>
34	Door handle LH - Front & Rear <i>Replaced</i>	2	\$134.00	268.00	<i>✓</i>
35	RH Lower arm <i>Replaced</i>	1	\$224.30	224.30	<i>✓</i>
	Total			\$18,359.40	
			Less 30%	\$5,507.82	
	Sub Total 1			\$12,851.58	

8826-80

6178-83-

Premium Carz Services Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
B	Spare Parts (Nett)				
1	Front bumper clip <i>new</i>	8	\$4.90	\$39.20	x
2	Front bumper side retainer RH <i>new</i>	1	\$35.20	\$35.20	x
3	Front bumper side retainer LH	1	\$35.20	\$35.20	x
4	Rear end panel garnish	1	\$82.00	\$82.00	x
5	Rear end panel garnish clip <i>new</i>	8	\$4.90	\$39.20	x
6	Rear fender inner trim clip <i>new</i>	16	\$4.90	\$78.40	-30
7	Exhaust silencer <i>new</i>	1	\$478.00	\$478.00	x
8	knuckle <i>new</i>	1	\$402.80	\$402.80	✓
9	Linkage <i>Broken - R.H.</i>	2	\$47.90	\$95.80	✓ 47.90
10	Axle <i>new</i>	1	\$452.60	\$452.60	x
	Total			\$1,738.40	
	Less 10%			\$173.84	
	Sub Total 2			\$1,564.56	
C.	Spare Parts (S/Nett)				
1	Shock absorber RH <i>Best</i>	1	\$310.90	\$310.90	✓
2	Shock absorber LH <i>Best</i>	2	\$310.90	\$310.90	x
3	Tyres front <i>ut</i>	2	\$350.00	\$700.00	780
4	Tyre rear <i>ut</i>	1	\$350.00	\$350.00	-180
5	Rims front <i>Best</i>	2	\$450.00	\$900.00	400
6	Rims rear	1	\$450.00	\$450.00	400
8	Drive shaft <i>Rh Dend.</i>	1	\$995.50	\$995.50	✓
	Sub-Total 3			\$3,021.80	
	Total for Parts			\$17,437.94	
D.	Labour				
1	To check wiring.			\$120.00	60
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,400.00	1200
3	Spray painting all affected parts & areas.			\$1,630.00	1200
4	To spray anti-rust undercoat.			\$120.00	100
5	To remove and refit door glass.			\$120.00	100
6	To remove and replace exhaust silencer.			\$180.00	x
7	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00	100
8	Wheel Alignment			\$100.00	80
	Total Labour			\$3,890.00	
	Total Repair Cost			\$21,327.94	

Adrian Lij
2/5 22/11/22

Yours faithfully,

(Signature)

Candice Yee

f Premium Carz Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Third party survey is allowed
- Insurance company must be resurveyed and
- Report to line a Insurance Company

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

12 Days -
Supplementary: 527.01
Total: 12755.77
L/S: 10210



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel: 6636 9100 Fax: 6636 9113

Date : 22-11-22

TO: AXA Insurance Pte Ltd
8 Shenton Way
#27-01 AXA TOWER
Singapore 068811

Our Customer : Chng Yai Wun
Vehicle No : SGJ6748B
Model : Nissan Latio 1.5L T
Manufacture Year : 2006
Date of Accident : 21-11-22
Total Estimate Repair Days : 10
Total Pages : 1

Attn : Motor Claims Department
Fax : 68804741

Re: Supplementary Repair Estimate For Third Party Claim against SGG4930U

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A	Spare Part				
1	LH Lower arm <i>But</i>	1	\$224.30	\$224.30	✓
2	Front RH weatherstrip <i>new</i>	1	\$110.50	\$110.50	✓
	Total			\$334.80	
	<i>224.30</i>				
	Less 30%			\$100.44	
	<i>157.01</i>				
	Sub-total 1			\$234.36	
C	Spare Parts (S/Nett)				
1	Drive Shaft LH <i>new</i>	1	\$995.50	\$995.50	✓
2	Front Cross member link RH <i>But</i>	1	\$150.20	\$150.20	✓
	Sub-total 2			\$1,145.70	
D.	Labour				
1	To remove and replace undercarriage RH			\$250.00	<i>220</i>
	Labour			\$250.00	
	Total Supplementary Repair Cost			\$1,630.06	<i>220</i>

Yours faithfully,


Candice Yee
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Supplementary: 527.01