



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
6453 2121 (4 lines) / 6458 1111 (24 hrs)
6459 9795 / 6459 0433
admin@vinsautogroup.com.sg
www.vinsautogroup.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/112022/5794
Policy No:	SP2002089108-01	Date of Loss:	21/11/2022
Vehicle Reg. No.:	SJR4293G	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	INDORIA RAHUL DEV	Contact No:	+6591277278
Driver:	INDORIA RAHUL DEV		
Make/Model:	TOYOTA LEXUS, 2.5 IS250 (A)	Vehicle Reg. Date:	24/06/2009
Vehicle Colour:	WHITE	Chassis No:	JTHBK262905099524
Engine No:	4GR0564314		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO THE SKE		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	10,211.00
Miscellaneous Items	0.00
Labour	2,070.00
Paintwork Labour	1,100.00
Towing	0.00
Gross Total (\$\$)	13,381.00
+ GST 7.00% (\$\$)	936.67
Nett Amount (\$\$)	14,317.67

This claim is handled by: **MUHAMMAD ISWAN BIN ISHAK**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 22 Nov 2022)

Parts: 143

TOYOTA LEXUS 2.5 IS250 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SJR4293G/22/11/2022 10:17

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RH SIDE MIRROR ASSY (ORDER) <i>broken</i>	0.00	0.00	*740.00 F ✓
2	1		*RH SIDE MIRROR SIGNAL LIGHT <i>broken</i>	0.00	0.00	*100.00 F ✓
3	1		*RH SIDE MIRROR GLASS <i>broken</i>	0.00	0.00	*240.00 F ✓
4	1		*FRONT RH DOOR <i>Deval</i>	0.00	0.00	*660.00 F ✓
5	1		*FRONT RH DOOR OUTER CHROME MOULDING <i>cut</i>	0.00	0.00	*120.00 F ✓
6	1		*FRONT RH DOOR OUTER HANDLE - LONG (ORDER) <i>cut</i>	0.00	0.00	*220.00 F ✓
7	1		*FRONT RH DOOR OUTER HANDLE - SHORT <i>key</i>	0.00	0.00	*40.00 F X
8	1		*FRONT RH DOOR INNER LOCK (ORDER) <i>key</i>	0.00	0.00	*310.00 F X
9	1		*FRONT RH DOOR RUBBER <i>key</i>	0.00	0.00	*180.00 F ✓
10	1		*FRONT RH DOOR POWER WINDOW MOTOR (ORDER) <i>key</i>	0.00	0.00	*310.00 F X
11	1		*FRONT RH DOOR POWER WINDOW GEAR ?	0.00	0.00	*170.00 F ✓
12	1		*REAR RH DOOR <i>Deval</i>	0.00	0.00	*620.00 F ✓
13	1		*REAR RH DOOR OUTER CHROME MOULDING <i>key</i>	0.00	0.00	*110.00 F X
14	1		*REAR RH DOOR TOP HINGE <i>key</i>	0.00	0.00	*60.00 F X
15	1		*REAR RH DOOR LOWER HINGE <i>key</i>	0.00	0.00	*60.00 F ✓
16	1		*REAR RH DOOR CHECK <i>key</i>	0.00	0.00	*130.00 F X
17	1		*REAR RH DOOR RUBBER <i>key</i>	0.00	0.00	*140.00 F ✓
18	1		*REAR RH DOOR INNER LOCK <i>key</i>	0.00	0.00	*280.00 F X
19	1		*REAR RH DOOR POWER WINDOW MOTOR (ORDER) <i>key</i>	0.00	0.00	*750.00 F X
20	1		*REAR RH DOOR POWER WINDOW GEAR ?	0.00	0.00	*120.00 F ✓
21	1		*REAR RH DOOR INNER TRIMBOARD (ORDER) <i>key</i>	0.00	0.00	*1,300.00 F X
22	1		*REAR RH FENDER (ORDER) <i>Deval</i>	0.00	0.00	*750.00 F ✓
23	1		*REAR RH FENDER INNER SHIELD <i>key</i>	0.00	0.00	*180.00 F X
24	10		*REAR RH FENDER INNER SHIELD CLIPS <i>key</i>	0.00	0.00	*20.00 F X
25	1		*REAR RH SPORT RIM (ORDER) <i>key cut</i>	0.00	0.00	*500.00 F ✓
26	1		*REAR RH KNUCKLE ARM <i>key</i>	0.00	0.00	*640.00 F X
27	1		*REAR RH WHEEL BEARING (ORDER) <i>key</i>	0.00	0.00	*370.00 F X
28	1		*REAR WINDSCREEN GLASS MOULDING <i>key</i>	0.00	0.00	*90.00 F ✓
29	1		*WINDSCREEN GLASS GUM <i>key</i>	0	0.00	*80.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 9,290.00
+ Margin on L,N Items 10.00% (\$\$) 921.00
Total Parts (\$\$) 10,211.00

Vin's Motor Pte Ltd/SJR4293G/22/11/2022 10:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO SPRAY PAINTING	New	1,100.00 800/-
Labour Items			
2	TO CHECK WHEEL ALIGNMENT	New	150.00 60/-
3	TO REMOVE AND REFIX WINDSCREEN GLASS	New	180.00 80/-
4	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	380.00 40/-
5	TO REMOVE AND REFIX ROOFLINING AND SEAT CUSHION	New	380.00 80/-
6	TO REPAIR DAMAGES	New	980.00 700/-
Gross Labour Cost (\$\$)			3,170.00

Vin's Motor Pte Ltd/SJR4293G/22/11/2022 10:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

23/11/2022 1430h

hkt Auto

1/5m 6 dgr.

Excess TDA.

Parts after reg.

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: