

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011724/UVP3Q2**Date:** 08/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00108952206
Claimant Vehicle No :	GBL9670U	Insured Vehicle No :	GBF3349U
Date of Loss:	19/11/2022	Nature of Claim: TP	Claim No: SNM22D208341/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL9670U	Engine No:	S07B4011257
Make & Model:	HONDA N-BOX, 658cc (A)	Chassis No:	JJ16001716
Reg. Date:	27/08/2022 (Man. Year: 2022)	Odometer:	218 km
Colour:	Blue		
Engine Capacity:	658 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	145/80 R12	Rear Tyre Size:	145/80 R12
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,353.20	3,353.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,230.00	380.00	23.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,963.20	4,583.20	380.00	7.66

INSPECTION

Date of Assignment:	22/11/2022	
Date Inspected:	22/11/2022	Inspected At: Skytech Auto Pte Ltd (HQ) 2 KAKI BUKIT AVE 2, #01-02 Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2022)
Parts:	144	HONDA N-BOX 658cc (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL9670U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT (WCP)	Distorted	1,950.00 F	*1,950.00 F
2	1		*REAR BOOT GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
3	1		*REAR BOOT EMBLEM (NPA)	Serviceable	0.00 F	*- F
4	1		*REAR BOOT N VAN WORDING (WCP)	Twisted	38.00 F	*38.00 F
5	1		*REAR BOOT 70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
6	1		*REAR BOOT 5 PAX STICKER	Necessary	10.00 FS	*10.00 FS
7	1		*REAR BOOT 350 KG STICKER (NPA)	Not Necessary	0.00 F	*- F
8	1		*REAR BOOT INNER RUBBER STOPPER (LEFT) (NPA)	Not Necessary	0.00 F	*- F
9	1		*LEFT TAILLAMP (WCP)	Cracked	420.00 F	*420.00 F
10	1		*LEFT ROLLER GUIDE STOPPER GARNISH (WCP)	Cracked	18.00 F	*18.00 F
11	1		*REAR BUMPER (N/S) (WCP)	Torn	285.00 F	*285.00 F
12	1		*REAR BUMPER CHIPS	Necessary	40.00 FS	*40.00 FS
13	1		*REAR BUMPER BRACKET (LEFT) (NPA)	Not Necessary	0.00 F	*- F
14	1		*REVERSE SENSOR (NPA)	Not Necessary	0.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,811.00	2,811.00
+ Margin on L,N Items 20.00/20.00% (S\$)	542.20	542.20
Total Parts (S\$)	3,353.20	3,353.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	GLASS FIXING	New	150.00	120.00
2	TRANSFER BOOT	New	150.00	60.00
3	ANTI RUST PROOF	New	80.00	30.00
4	CHECK WIRING	New	80.00	20.00
5	PANEL BEATING	New	450.00	400.00
6	PAINT WORK	New	700.00	600.00
Gross Labour Cost (S\$)			1,610.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >