



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 8823E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DEFORMED	1,861.00	1,861.00
1	FRONT BUMPER SIDE HOLDER RH	NOT NECESSARY	98.00	-
1	FRONT BUMPER SENSOR RH	DAMAGED	295.00	295.00
1	FRONT BUMPER LOWER CHROME MOULDING RH	NOT NECESSARY	145.00	-
1	HEADLAMP RH	CRACKED	5,947.00	5,947.00
1	HEADLAMP LOWER BRACKET RH	NOT NECESSARY	68.00	-
1	FRONT RH FENDER	DENTED	1,298.00	1,298.00
1	FRONT RH FENDER INNER SHIELD	DEFORMED	242.00	242.00
1	BONNET (ALUMINIUM)	DENTED	3,043.00	3,043.00
1	BONNET LOGO	NECESSARY	65.00	65.00
1	FRONT RH WHEEL RIM	NOT NECESSARY	1,540.00	-
1	FRONT RH TYRE	NOT NECESSARY	350.00	-
	LESS 10% DISCOUNT		-	-1,275.10
			14,952.00	11,475.90
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT RH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	30.00	30.00
			80.00	80.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		1,000.00	800.00
	SPRAY PAINTING.		1,000.00	700.00
	WIRING.		50.00	30.00
	TO APPLY TUFF COAT.		150.00	50.00
	TO PERFORM DIAGNOSTIC TEST.		200.00	120.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			2,550.00	1,700.00
	<b>GRAND TOTAL</b>		<b>17,582.00</b>	<b>13,255.90</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>10,600.00</b>
---	--	--	------------------

Report Ref No. CS/LPC22011730/Awy3e2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**