



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22011730/Awy3e2 Date: 09/03/2023 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 3781D	Veh. Inspected	SMT 8823E	
Policy No.		Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026615	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	22/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 730LI	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA7E02010G245360	Colour	BLACK	
Odometer	85610 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	MICHELIN	6 mm	
L/H Front Tyre	245/50 R18	MICHELIN	6 mm	
R/H Rear Tyre	245/50 R18	MICHELIN	6 mm	
L/H Rear Tyre	245/50 R18	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/11/2022	Inspection Date	23/11/2022	
Survey held at	2020 SPRAY PAINTING PTE LTD 8 KAKI BUKIT AVENUE 4, #03-19, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	