

2020 spy Part SMT8823E. 2017 Dec.

TP Lon Pac C.

BMW 730Li 1998 cc

Xin Ya.

WBA7E02 010G245360.

Front Bumper.	Deformed	1861	✓
Front Bumper Clips	MP	50(SN)	✓
Front Bumper Side Holder RH.	MP m	98	X
Front Bumper Sensor RH.	Damaged	295	✓
Front Bumper lower Chrome Moulding RH.	MP m	145	X
Headlamp RH.	Cracked	5947	✓
Headlamp lower Bracket RH.	MP m	68	X
Front RH Fender	Dented	1298	✓
Front RH Fender Inner Shield	Deformed	242	✓
Front RH Fender Inner Shield clips.	MP	30(SN)	✓
Bonnet (Aluminium)	Dented	3043	✓
Bonnet Logo	MP	65	✓
Front RH Wheel Rim.	2	1540	X
Front RH Tyre.	MP MP	350	X

SMT 8823 E.

Panel Beating.

~~1000~~ 800

Spray Painting

~~1000~~ 700

Wiring.

~~50~~ 30

To apply tuff coat.

~~150~~ 50

To perform diagnostic test

~~200~~ 120

To perform wheel alignment.

150. X.

hist: 12751

Labour: 17.00

ten 10% 11475.80

total: 13255.90

S.N: 80

L/S: 10.6K

05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: