

BUL
NCC
NCC
NEL
?XNN
?XNN
?BR
?cut
Cra
?Lra
?Cra
xNN
- NEL
- NEL
x NN
NEL
x NN
~~CRA~~ CRA
x NN
x NN
- Cra
- CCR
x }
x }
x }
x }
x }
x }
x }
x }
BUL
x NN
✓ BR
x }
x }
x }
x }
x }

NN
NN
NN

39	LH taillamp lock clips	1set	\$	15.00	X NN
40	Rear compartment trim box	1	\$	223.00	X NN
41	Rear RH fender inner trim board	1	\$	400 421.00	X L1a
42	Rear LH fender inner trim board	1	\$	400 421.00	X L1a
			\$	8,134.00	4144
			Parts less 10%	\$ 813.40	828
			Total	\$ 7,320.60	3316

No.	Special Nett Items	Qty	Amount S\$	
1	Tailgate windscreen glass sealant	1	\$ 80.00	50
2	Tailgate windscreen glass inner seal	1	\$ 60.00	30
3	Tailgate inner trim board clips	1	\$ 50 80.00	50 net
4	Tailgate "C&C" emblem	1	\$ 120.00	Net 45
5	Tailgate reverse camera	1	\$ 680.00	X NN
6	Rear bumper clips	1set	\$ 80.00	net 40
7	Rear fender RH inner board clips	1set	\$ 70.00	30
8	Rear fender LH inner board clips	1set	\$ 70.00	30
9	End panel joint sealant	1	\$ 70.00	X NN
10	Rear number plate	1	\$ 70.00	X NN
			Total:	\$ 1,380.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00	600
2	Spray painting on affected areas and panels	\$ 1,200.00	600
3	Check wiring and lighting system on affected areas	\$ 80.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 100.00	X
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 240.00	X
6	Remove and replace tailgate inner parts to new tailgate	\$ 180.00	X
7	Remove and replace tailgate reverse camera to assist repair	\$ 100.00	X
8	Remove and replace rear inner trims, garnish, boards and mat to assist repair	\$ 320.00	X
9	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00	30

Total: \$ 3,720.00

4941

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 7,320.60

Special Nett: \$ 1,380.00

Labour: \$ 3,720.00

Total Amount: \$ 12,420.60

1 ref 20097659
L/S After repair
 23/11/22

Total = 48.51

20% = 970

5 days.

= 3881

Final T ≈ 3900

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: