

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ 1,219.00
2	Tailgate "CRDI" emblem	1	\$ 20 33.00
3	Tailgate "Carens" emblem	1	\$ 20 42.00
4	Tailgate centre emblem	1	\$ 56.00
5	Tailgate lock	1	\$ X 112.00
6	Tailgate lock catch	1	\$ X 35.00
7	Tailgate inner trim board	1	\$ 200 378.00
8	Tailgate weatherstrip	1	\$ 134.00
9	Rear bumper top	1	\$ 576.00
10	Rear bumper lower	1	\$ 180 231.00
11	Rear bumper centre skid plate garnish	1	\$ 150 182.00
12	Rear bumper RH side reverse sensor	1	\$ X 167.00
13	Rear bumper RH reverse sensor	1	\$ 167.00
14	Rear bumper LH reverse sensor	1	\$ 167.00
15	Rear bumper LH side reverse sensor	1	\$ X 167.00
16	Rear bumper reverse sensor holders	4	\$ 22.00
17	Rear bumper reverse sensor wire harness	1	\$ X 251.00
18	Rear bumper reinforcement	1	\$ 300 367.00
19	Rear bumper reinforcement RH bracket	1	\$ X 167.00
20	Rear bumper reinforcement LH bracket	1	\$ X 167.00
21	Rear bumper RH bracket	1	\$ 22.00
22	Rear bumper LH bracket	1	\$ 22.00
23	Rear bumper RH lower bracket	1	\$ X 18.00
24	Rear bumper LH lower bracket	1	\$ X 18.00
25	Rear bumper centre bracket	1	\$ X 37.00
26	Rear bumper RH fog lamp	1	\$ X 127.00
27	Rear bumper LH fog lamp	1	\$ X 127.00
28	Rear bumper RH side retainer	1	\$ X 27.00
29	Rear bumper LH side retainer	1	\$ X 27.00
30	Rear bumper towing cover	1	\$ X 16.00
31	End panel	1	\$ R 543.00
32	End lower panel	1	\$ X 188.00
33	End panel inner garnish	1	\$ 89.00
34	RH taillamp assy	1	\$ X 456.00
35	RH taillamp panel	1	\$ X 113.00
36	RH taillamp lock clips	1set	\$ X 15.00
37	LH taillamp assy	1	\$ X 456.00
38	LH taillamp panel	1	\$ X 113.00

39	LH taillamp lock clips	1set	\$ 15.00
40	Rear compartment trim box	1	\$ 223.00
41	Rear RH fender inner trim board	1	\$ 400 421.00
42	Rear LH fender inner trim board	1	\$ 400 421.00

\$ 8,134.00
 Parts less 10% \$ 813.40
 Total \$ 7,320.60

X NN
 X NN
 ✓ 150
 ✓ 400

4088
 408.80
 3679.20

No.	Special Nett Items	Qty	Amount S\$
1	Tailgate windscreen glass sealant	1	\$ 80.00
2	Tailgate windscreen glass inner seal	1	\$ 60.00
3	Tailgate inner trim board clips	1	\$ 50 80.00
4	Tailgate "C&C" emblem	1	\$ 120.00
5	Tailgate reverse camera	1	\$ 680.00
6	Rear bumper clips	1set	\$ 80.00
7	Rear fender RH inner board clips	1set	\$ 70.00
8	Rear fender LH inner board clips	1set	\$ 70.00
9	End panel joint sealant	1	\$ 70.00
10	Rear number plate	1	\$ 70.00

Total: \$ 1,380.00

✓ 50 NEC
 ✓ 30 NEC
 ✓ 150
 ✓ 45
 X NN
 ✓ 40
 30 nec
 30 nec
 X NN
 X NN

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 100.00
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 240.00
6	Remove and replace tailgate inner parts to new tailgate	\$ 180.00
7	Remove and replace tailgate reverse camera to assist repair	\$ 100.00
8	Remove and replace rear inner trims, garnish, boards and mat to assist repair	\$ 320.00
9	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00

600

600

30

✓ 60

✓ 120

✓ 60

✓ 50

✓ 60

✓ 50

Total: \$ 3,720.00

4941

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 7,320.60

Special Nett: \$ 1,380.00

Labour: \$ 3,720.00

Total Amount: \$ 12,420.60

1 ref 21097659
L/S After repair
23/11/22

5 days.

Total = 48.51

20% = 9.70

= 38.81

Final T ≈ 3900

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total = 5584.20

20% = 1116.84

FT = 4467.36

≈ 4450

I/s \$4200