

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

LOH HWEE PENG PATRICIA
C/O 46 LENTOR PLAIN
SINGAPORE 786548

*Not authorized
11/11/2022
Penny Aun Paim
P. 1 day*

Date : 22/11/2022

QUANTITY	PARTICULARS	AMT (\$)
RE : HONDA VEZEL / SLC 4876 E		
1pc	rear bumper center pad <i>762</i>	897.62 ✓
2 pcs	rear bumper side pad <i>8182</i> <i>N/Sux</i> <i>o/s mgcm</i>	866.40 ✓
16 pcs	rear bumper clip	51.20 ✓
2 pcs	rear bumper side retainer	157.80 X
2 pcs	rear bumper reflector	592.80 X
1pc	rear bumper lower dust cover	422.10 X
1pc	rear end outer panel	863.74 X
1pc	rear end inner sub panel	552.30 X
1pc	rear end panel trim <i>266</i>	363.20 ✓
1 pc	rear remote lock buzzer	265.40 X
1pc	rear remote lock sensor	314.80 X
1pc	rear tail door lock catch	84.60 X
1 pc	rear tail door emblem "VEZEL"	67.50 ✓
1pc	rear tail door emblem "LOGO"	62.80 X
1pc	rear tail door weatherstrip	369.51 X
1pc	rear tail door glass moulding <i>112</i>	269.40 ✓
1pc	rear tail door outer garnish	598.74 X
2 pcs	rear tail door lamp	1,197.20 X
2 pcs	rear tail lamp	1,096.20 X
3 pcs	rear tail lamp clip	10.80 X
3 pcs	rear tail lamp clip gormet	8.55 X
1pc	rear tail lamp housing panel	561.00 X
1pc	rear tail door <i>953</i>	1,693.50 ✓
1pc	rear tail door inner trim	568.65 X
1pc	rear tail door servo lifter LH	354.11 X
1pc	rear tail door rubber stopper LH	16.20 X
1pc	rear tail door lock <i>145</i>	215.40 ✓
1pc	rear fender arch protector <i>o/s</i>	196.40 ✓
1pc	rear fender arch protector clip	28.80 ✓
1pc	rear fender dust cover	186.70 X
1pc	rear fender dust cover clip	29.60 X
	sub total	12,963.02
	less 20%	2,592.60
	sub total	10,370.42

Aspire 3

DDR4

Faster memory speed

Precision touchpad

802.11a

Faster wireless

Intel® Celeron® processor N4020

Intel® UHD Graphics

4 GB DDR4 Memory

128GB SSD

	BALANCE CARRIED FORWARD		10,370.42	
1 set	reverse sensor	s.nett	shom 250.00	2000
1 pc	rear tail door glass inner seal	s.nett	na 45.00	3000
1 tube	windscreen glass sealant	s.nett	na 65.00	4000
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		1,000.00	500
	To check wiring system.		60.00	20
	To apply rust proofing on affected areas.		120.00	30
	To apply waterproof sealant on affected areas.		na 120.00	1
	To apply putty and spray painting on affected areas. (12 surfaces)		950.00	700
	To install reverse sensors and reverse camera.		120.00	50
	To remove rear glass to enable repair.		150.00	120
	To remove carpet , trimming and seats to enable repair.		120.00	50
	To transfer tail door accessories.		60.00	✓
	Total		13,430.42	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: