

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunus Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 22 Nov 2022

**Preliminary Advice**

|                    |                  |                         |                     |
|--------------------|------------------|-------------------------|---------------------|
| Vehicle No         | : SGM40H         | Accident Date           | : 14/11/2022        |
| Make               | : SUBARU IMPREZA | Policy No.              | : JF1SJGK85GG070809 |
| Assignment Date    | : 22/11/2022     | Excess                  | : S\$0.00           |
| Date of Inspection | : 22/11/2022     | Est. Duration of Repair | : 5                 |
| Inspection At      | :                |                         |                     |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 11,454.70 |
| Revised Amount              | :S\$ | 5,213.50  |
| Check Items (Estimated)     | :S\$ | 3,423.20  |
| Total                       | :S\$ | 8,636.70  |
| Lump Sum Repair             | :S\$ |           |

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 65,000.00 |
| COE / PARF Rebate  | :S\$ | 28,499.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 36,501.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by part repair as repairer unable to locate 2nd hand parts.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .