

ASS. REC. BY:

REF: CS/CT/22011738/Gnp3

ASSIGNMENT

19/9/2016

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 0
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$54,000
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL6 2317 ✓ Yr Regn: 1 ✓
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda vezel c.c. 1496 ✓
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: R4 11203719
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60 R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or BESTLAK RADIAL RP18
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 11/11/2022 D.O.I. 23/11/2022
 Survey held at SPACE CAR CARE
 Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NET VALUE \$27,000 ✓

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

\$ - RS - \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.J. (\$) _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SLG231X Case Owner : JOHARI
Make & Model : HONDA VEZEL Year Manufacture : _____
Chassis No : RU11203719 Engine No : L15B4403719
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
①	Front bumper / <i>re</i>	1		\$ 901.70	/		✓
②	Front bumper side retainer / <i>wt</i>	2	2X	\$ 15.00	30 ✓	4	✓
③	Front bumper clip / <i>mc</i>	10		\$ 39.00	/		✓
④	Front bumper lower bumper / <i>re</i>	1		\$ 229.90	/		✓
5	Front bumper reinforcement ? X nn	1		\$ 298.60			✓
6	Front bumper sponge ? X nn	1					✓
7	Front bumper tow cover X nn	1		\$ 25.98			✓
8	Front headlamp RH ? X nn	1		\$ 1,997.60			✓
9	Front headlamp bracket RH ? ✓ BR	1		\$ 33.90	/		✓
10	Front fog lamp RH ? X nn	1		\$ 331.80			✓
11	Front fog lamp cover RH ? X nn	1		\$ 38.40			✓
12	Front fender arch RH ? X nn	1		\$ 98.00			✓
⑬	Rear windscreen / <i>sm</i>	1		\$ 1,250.10	/		✓
⑭	Rear windscreen seal (1set) / <i>mc</i>	1		\$ 138.00	/		✓
⑮	Rear top spoiler ? photo? BR	1		\$ 408.60	/		✓
⑯	Rear top spoiler third brake light ? X nn	1		\$ 280.00			✓
⑰	Rear camera X nn	1				\$ 550.00	✓
⑱	Tailgate / <i>dis</i>	1		\$ 1,100.90	/		✓
⑲	Tailgate rubber (@ body) ? photo? CRU	1		\$ 96.80	/		✓
⑳	Tailgate lock / <i>im</i>	1		\$ 96.80	/		✓
㉑	Tailgate lock catch X BT	1		\$ 27.00	/		✓
㉒	Tailgate hinge / <i>BT</i>	2		\$ 80.20	/		✓
23	Tailgate lock sensor ? X nn	1		\$ 220.00			✓
㉔	Tailgate absorber ? photo? BT	2		\$ 180.00	/		✓
㉕	Tailgate outer garnish ? BR	1		\$ 220.00	/		✓
㉖	Tailgate lamp / <i>CRA</i>	2		\$ 575.20	/		✓
㉗	Tailgate emblem / <i>mc</i>	1		\$ 27.00	/		✓
㉘	Tailgate Vezel wording / <i>mc</i>	1		\$ 45.00	/		✓
㉙	Tailgate inner trimboard ? photo?	1	CRU	\$ 120.70	/		✓
㉚	Tailgate inner side trim RH ? photo?	1	CRU	\$ 38.20	/		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SLG231XCase Owner : JOHARIMake & Model : HONDA VEZEL

Year Manufacture : _____

Chassis No : RU11203719Engine No : L15B4403719

Sales Order : _____

Supplier : _____

Order By : _____

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
31	Tailgate inner side trim LH ? photo?	1	CRU	\$ 38.20	/		
32	Tailgate inner center trim ? photo?	1	CRU	\$ 70.50	/		
33	Tail gate wiper motor ? X nn	1		\$ 205.00			
34	Tailgate wiper arm ? X nn	1		\$ 72.00			
35	Tailgate wiper blade ? X nn	1		\$ 48.60			
36	Rear bumper / Dis	1		\$ 553.60	/		
37	Rear bumper clip / MCL	10		\$ 39.00	/		
38	Rear bumper side retainer RH / Dis	1		\$ 17.00	/		
39	Rear bumper side reflexer lamp RH / lost	1		\$ 145.80	/		
40	Rear bumper reinforcement / ST ? X	1	nn				
41	Rear bumper sponge ? X nn	1					
42	RHR bumper cover (71502-T7A-000) / Dis	1		\$ 172.60	/		
43	End panel / Dis	1		\$ 411.90	/		
44	End panel top garnish / RL	1		\$ 66.60	/		
45	Spare tyre panel ? photo? X	1	repair	\$ 741.45	/ X		
46	Spare tyre panel inner trime board ? photo?	1		\$ 225.70	/ X		
47	RHR tail lamp / Dis	1		\$ 530.90	/		
48	RHR fender / Dis	1		\$ 931.80	/		
49	RHR fender cowlng / RL	1		\$ 98.70	/		
50	RHR fender cowlng clip / MCL	8		\$ 31.90	/		
51	RHR fender arch / Dis	1		\$ 119.00	/		
52	RHR fender top garnish ? photo?	1	CRU	\$ 220.00	/		
53	RHR fender inner trim ? photo?	1	CRU	\$ 250.70	/		
54	RHR fender inner trim center ? photo?	1	CRU	\$ 240.00	/		
55	RHR Fender inner trim top ? photo?	1	CRU	\$ 40.50	/		
56	RHR fender inner trim clip ?	16					
57	RHR fender air vent / Dis	1		\$ 28.00	/		
58	RHR door X Repair	1		\$ 930.60			
59	RHR door rubber X NN	1		\$ 80.70			
60	RHR door transparent sticker / MCL	1		\$ 28.00	/		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

18/11/2022

3978.70

5001-85

10:14 AM

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SLG231X Case Owner : JOHARI

Make & Model : HONDA VEZEL Year Manufacture : 01/00/00

Chassis No : RU11203719 Engine No : L15B4403719

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyor
61	RHR door lock ? photo? X nn	1		\$ 220.40			
62	RHR door outer moulding X	1		\$ 60.50			
63	Rear exhaust box X	1		\$ 528.00			
64	Rear exhaust mounting X	1		\$ 17.10			
65	Rear exhaust bracket X	1		\$ 150.00			
66	RHR shock absorber ? X nn	1		\$ 385.00			
67	RHR rear wheel bearing ? X nn	1		\$ 342.90			
68	RHR wheel hub ? X nn	1		\$ 342.90			
69	Sport rim X	1				\$ 836.20	
70	Tyre 215/60 R 16 X	1				\$ 350.00	X
71	Reverse sensor / Dis	1			200 ✓	\$ 480.00	
72	Inner seal /	1			50 ✓	\$ 60.00	
73	Sealant /	1			40 ✓	\$ 80.00	
74							
75							
76							
77							
78							
79							
80							
81							
82							
83							
84							
85							
86							
87							
88							
89							
90							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

290 nett

18/11/2022

10:14 AM

Tel: 63837168 / 63837466 Fax: 62815767

SLG 231 X

Case Owner _____ ;

Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

11366.33

2370 ✓