

TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

Attn: Motor Claims Department

Prepared By : Hoe

S/N	Description	Qty	Unit Amount (\$\$)	Amount (\$\$)
	<u>Parts (List)</u>			
1	Front Windscreen	1	980.30	980.30 <i>cut</i>
2	Front Windscreen Weatherstrip	1	391.50	228.90 391.50 <i>cut</i>
3	A-pillar outer	1	433.90	389 433.90 <i>bt</i>
4	A-pillar inner	1	371.20	371.20 <i>Rx</i>
5	A-pillar inner trim	1	216.70	216.70 <i>Rx</i>
6	Mirror Stay c/w Side Mirror	1	737.00	636.40 737.00 <i>bno</i>
7	Round Mirror	1	145.50	145.50 <i>mis</i>
8	Centre Panel <i>Black moulding LH</i>	1	350.80	195.90 350.80 <i>cut</i>
9	Mirror Stay Cap	1	49.50	49.50 <i>mis</i>
10	Mirror Stay Cover	1	198.50	198.50 <i>mis</i>
11	Black Trim, LH	1	113.50	113.50 <i>mis</i>
12	Headlamp, LH	1	979.00	727.10 979.00 <i>cut</i>
13	Front Door, LH	1	1,902.20	1280 1,902.20 <i>bt</i>
14	Front Door Qtr Trim, LH	1	28.60	28.60 <i>de</i>
15	Window Glass, LH Door	1	733.70	408 733.70 <i>bno</i>
16	Window Channel	1	258.40	111 258.40 <i>de</i>
17	Front Door Weatherstrip, LH	1	217.30	146 217.30 <i>fu</i>
18	Front Door Frame Seal	1	92.70	92.70 <i>cut</i>
19	Front Bumper	1	658.50	658.50 <i>Rx</i>
20	ERP Bracket	1	80.00	80.00 <i>net</i>
21	Dashboard	1	1,595.80	1,595.80 <i>Rx</i>
22	Door Trim, LH	1	438.90	438.90 <i>de</i>
				10,973.50
			Less: 25%	(2,743.38)
			Price after disc	8,230.13
				6169.80
				4627.35
				SN 26
	<u>Parts (Nett)</u>			
1	ROV Sticker	1	20.00	20.00 <i>net</i>
			Parts total	8,250.13

SIN SHENG AUTO WORKSHOP PTE LTD
REGISTRATION NO.: 202019500G
NO. 5 TUAS AVE 3 SINGAPORE 639405
TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

Labour charges

To dismantle/replace front windscreen
To dismantle/replace dashboard
To panel beat/repair LH body
To dismantle/replace abovementioned parts
To spray painting on repaired areas

	120.00	✓
	250.00	1802 ^{un} info.
	950.00	750
	950.00	700
		1570
Labour total	2,270.00	

TOTAL 10,520.13

Hoe

Quek Beng Hoe

Tanfilm 97445749 / 62563561

Not Authorise 23/11/22 @ 520pm 4/5 \$5000

Exp: to be advise

4/5 Resury after repair

Tanfilm @ Thehard.com
27 days

4627-35

26

20

1570

6243-35

17 days
X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: