



SIN SHENG AUTO WORKSHOP PTE LTD

REGISTRATION NO.: 202019500G

NO. 5 TUAS AVE 3 SINGAPORE 639405

TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

Labour charges

To dismantle/replace front windscreen

120.00 ✓

To dismantle/replace dashboard

250.00 180? p.m/f.

To panel beat/repair LH body

950.00 750

To dismantle/replace abovementioned parts

950.00 700

To spray painting on repaired areas

Labour total 2,270.00

TOTAL 10,520.13

*Hoe*

Quek Beng Hoe

Tanfilm 97445749 / 62563561

Not authorized 23/11/22 @ 520pm

Exp: to be advise

1/5 Resurvey after repair

tanfilm@tuhar.com

27 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: