

India International Insurance Pte Ltd

64 Cecil Street
 #04/#05 IOB Building
 Singapore 049 711
 Attn: Motor Claims Department

Estimate No : ES2022/0079
 Date : 21/11/2022
 Vehicle No : GBF 5380P
 Make/Model : TOYOTA DYNA 150 MANUAL
 Date of Accident : 18/11/2022
 Prepared By : Hoe

S/N	Description	Qty	Unit Amount (\$\$)	Amount (\$\$)
<u>Parts (List)</u>				
1	Front Windscreen	1	980.30	980.30
2	Front Windscreen Weatherstrip	1	391.50	391.50
3	A-pillar outer	1	433.90	433.90
4	A-pillar inner	1	371.20	371.20
5	A-pillar inner trim	1	216.70	216.70
6	Mirror Stay c/w Side Mirror	1	737.00	737.00
7	Round Mirror	1	145.50	145.50
8	Centre Panel	1	350.80	350.80
9	Mirror Stay Cap	1	49.50	49.50
10	Mirror Stay Cover	1	198.50	198.50
11	Black Trim, LH	1	113.50	113.50
12	Headlamp, LH	1	979.00	979.00
13	Front Door, LH	1	1,902.20	1,902.20
14	Front Door Qtr Trim, LH	1	28.60	28.60
15	Window Glass, LH Door	1	733.70	733.70
16	Window Channel	1	258.40	258.40
17	Front Door Weatherstrip, LH	1	217.30	217.30
18	Front Door Frame Seal	1	92.70	92.70
19	Front Bumper	1	658.50	658.50
20	ERP Bracket	1	80.00	80.00
21	Dashboard	1	1,595.80	1,595.80
22	Door Trim, LH	1	438.90	438.90
				4,967.40
				Less: 25%
				(1,241.85)
				Price after disc
				3,725.55
<u>Parts (Nett)</u>				
1	ROV Sticker	1	20.00	20.00
Parts total				3,745.55

SIN SHENG AUTO WORKSHOP PTE LTD
REGISTRATION NO.: 202019500G
NO. 5 TUAS AVE 3 SINGAPORE 639405
TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

Labour charges

To dismantle/replace front windscreen	120.00
To dismantle/replace dashboard	250.00
To panel beat/repair LH body	950.00
To dismantle/replace abovementioned parts	
To spray painting on repaired areas	950.00

Labour total 2,270.00

TOTAL 6,015.55

Hoe

Quek Beng Hoe