



樹發汽車修理廠 SHU FATT AUTO WORKS

Appointed for repair
12/12/22

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo
4th November 2022

TP

SCK 9779 J TOYOTA CAMRY

		SS	
Spare Parts	1 Rear bumper.	526.50	Rx
	1 Set rear bumper clips.	60.00	net
	2 Rear bumper side retainers. @\$134.30	268.60	x nn
	1 Left rear bumper sensor.	393.60	x nn

		1248.70	60
Less 25%		312.17	45

		936.53	
Labour	To knock, straighten rear support panel, left rear fender, renew rear bumper and assembly.	450.00	200
	To respray damaged parts.	450.00	220
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.	80.00	x nn
	To reseal joints, reinsulate, anti rust panels and assembly.	60.00	x nn

		1976.53	420
		=====	
		420	
		45	
		\$465.2 days #	
AXVA70R- MR2B63HKX04002337			

Taufik 97495749
up' 24/11/22 @ 1120
2 days
Busy after upsk
Taufik e Mhant. on

MR: \$465.00