

ASS. REC BY: Taufik

REF:

03/10/22 011744 HWS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SKW 303A

Policy No. _____

Claims No. DMPC2200527H/ST

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$115K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Plat

Veh No: SCK 9779J

Yr Regn: 2019, June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Camry

C.C. 2487

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 58813

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 2563 HKX 04002337

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45R18

R: A -

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 2/11/2022

D.O.L. 24/11/22

Survey held at Shu Jett

Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

16/12/22 | Taufik informed final fig \$465 (Red 1511.53, 76%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 22/12/22-typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

S + RS. SI

☐ : Interview (\$)

Photos

☐ : Tech. Insp (\$)

Others

Report Formed: Merimen



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo
4th November 2022

TP

SCK 9779 J TOYOTA CAMRY

		S\$
Spare Parts	1 Rear bumper.	526.50 <i>Rx</i>
	1 Set rear bumper clips.	60.00 <i>rev</i>
	2 Rear bumper side retainers. @\$134.30	268.60 <i>x nn</i>
	1 Left rear bumper sensor.	393.60 <i>x nn</i>

		1248.70
		Less 25% 312.17

		936.53
Labour	To knock, straighten rear support panel, left rear fender, renew rear bumper and assembly.	450.00 <i>200</i>
	To respray damaged parts.	450.00 <i>220</i>
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.	80.00 <i>x nn</i>
	To reseal joints, reinsulate, anti rust panels and assembly.	60.00 <i>x nn</i>

		1976.53
		=====

AXVA70R- MR2B63HKX04002337

Taufik 97495749
wp' 24/11/22 @ 1120
2 days
Bring after work
Taufik e (Mhandi) on

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: