



樹發汽車修理廠 SHU FATT AUTO WORKS

Appointed for repair
12/12/22

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo
4th November 2022

TP

SCK 9779 J TOYOTA CAMRY

		SS
Spare Parts	1 Rear bumper.	526.50 <i>Rp</i>
	1 Set rear bumper clips.	60.00 <i>net</i>
	2 Rear bumper side retainers. @\$134.30	268.60 <i>x</i>
	1 Left rear bumper sensor.	393.60 <i>x</i>

		1248.70
		Less 25%
		312.17

		936.53
Labour	To knock, straighten rear support panel, left rear fender, renew rear bumper and assembly.	450.00 <i>200</i>
	To respray damaged parts.	450.00 <i>220</i>
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.	80.00 <i>x</i>
	To reseal joints, reinsulate, anti rust panels and assembly.	60.00 <i>x</i>

		1976.53
		=====

AXVA70R- MR2B63HKX04002337

Taufik 97495749

MR: \$465.00

up' 24/11/22 @ 1120

2 days

Busy after work

Taufik e Mhantou