



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI22011746/Twy3e2 Date: 23/03/2023  Code: GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMA 7759P	Veh. Inspected	SMG 8264L
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001271	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	22/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MAZDA 6	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JM6GL1072K0311105	Colour	RED
Odometer	42672 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	16/11/2022	Inspection Date	23/11/2022
Survey held at	48 Toh Guan Road East, #02-146 Enterprise Hub,		
Repairer	AUTOMOTIVE REPAIR CENTRE PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	