



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C


Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2211-627-TG
DATE : 21-Nov-2022
POLICY NO. :
VEHICLE REG. NO. : SMG8264L
VEHICLE MAKE : MAZDA6 SEDAN 2.0 AT STANDARD 2WD
JM6GL107ZK0311105

TO Motor Claim Department
QBE INSURANCE (SINGAPORE) PTE LTD
1 Wallich St, #35-01 Guoco Tower, Singapore 078881
Tel: +65 6224 6633

FOR SURVEYOR



ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			1009
1	Rear Bumper	1	\$ 1,185.00	\$ 1,185.00
2	Rear Bumper Side Retainer LH/RH	2	\$ 62.50	\$ 125.00
3	Rear Bumper Reinforcement	1	\$ 525.80	\$ 525.80
4	Rear Bumper Towing Cover LH/RH	2	\$ 66.00	\$ 132.00
5	Rear Boot	1	\$ 970.50	\$ 970.50
6	Rear Boot Emblem	1	\$ 75.80	\$ 75.80
7	Rear Boot Lock	1	\$ 235.10	\$ 235.10
8	Rear Boot Weatherstrip	1	\$ 185.20	\$ 185.20
9	Rear Boot Logo (Mazda)	1	\$ 54.70	\$ 54.70
10	Rear Boot Logo (6)	1	\$ 39.50	\$ 39.50
11	Rear Boot Logo (Skyactive)	1	\$ 106.80	\$ 106.80
12	Rear Boot Hinge LH/RH	2	\$ 310.50	\$ 621.00
13	Rear End Panel	1	\$ 725.80	\$ 725.80
14	Rear End Panel Top	1	\$ 358.30	\$ 358.30
	Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			Parts Less 20%
	• To display damaged part(s) during resurvey			Total Spare Parts
	• Parts prices are subject to confirmation			\$ (1,068.10)
	• Third party survey is on a "Without Prejudice" basis			\$ 4,272.40
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	SPECIAL NETT			
15	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
16	Rear Reverse Sensor	1	\$ 200.00	\$ 200.00
				Total Special Nett
				\$ 250.00
	LABOUR			
	Acknowledged by Repairer			
17	Remove, Refit and Repair Affected Accident Parts	1	\$ 800.00	\$ 800.00
18	Spray Paint (Rear Bumper, Rear Boot, Rear End Panel)	1	\$ 800.00	\$ 800.00
19	Remove & Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
20	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
21	Check and rectify electrical wiring	1	\$ 50.00	\$ 50.00

Estimate prepared by: JAMES TAN

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour \$ 1,830.00
Amount Before Excess \$ 6,352.40
Add GST @ 7% 444.67
Total Amount Payable \$ 6,797.07

Tan Jiah 97495749
wp 23/11/22 @ 1250
Tan Jiah @ 11hantouan
5 days
p/p Resurvey before paint

2331-28
230
1290
\$3851-28
05 days