



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR XE6348Y

Sembwaste Pte Ltd

30 Hill Street  
#05-04  
Singapore 179360

Home: 68546221Eric

### Vehicle & Document Information

WIP No 59117  
Reg No/Reg Date XE6348Y / 19/03/2021  
Date In/Mileage 39779  
Chassis No W1T964045204859875  
Engine No 470913C0596606  
Make/Model MBCV/Arocs 3236L ENA 8X2/4 515  
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
CSC00003	Cash	15/11/2022/ 16:28	JAC	610 / Philip Cheong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z Complaint ACCIDENT REPAIR				
A 00940101 TO REMOVE , REPLACE REPAIR INSTALL & WELD FRONT DAMAGED				6000.00
A 00940101 TO PUTTY & SPARY PAINTING				3000.00
A 00940101 TO REMOVE & REFIT FRONT DASNBOARD				750.00
A 00940101 TO REMOVE & REFITWIRE & HARNES				750.00
A 00940101 TO REMOVE AND REPLACE RADIATOR AND INTER COOLER				900.00
A 00940101 TO REMOVE AND REPLACE AIR CON CONDENSOR AND TOP UP GONGAS				450.00
A 00940101 TO REMOVE & REPLACE CHASSIS CROSSMEMBER AND REPAIR CHASSIS				3750.00
A 00940101 TO REMOVE & REPLACE AIR CON BLOWER AND HEATER UNIT				750.00
A 00940101 TO REMOVE & REFIT FRONT WINDSCREEN GLASS				984.00
A 00940101 TO REMOVE & REFIT INNER CARPET AND INNER TRIM				528.00
M SCREW	1.00	4.12	20.00	3.30
M SCREW	3.00	4.12	20.00	9.89
M PIPE CLAMP	2.00	14.70	20.00	23.52
M CLAMP	1.00	2.14	20.00	1.71
M SPREADER NUT	4.00	0.88	20.00	2.82
M SPREADER NUT	4.00	0.88	20.00	2.82
M TS WIPER BLADE	1.00	112.43	20.00	89.94
M STOP BUFFER	2.00	1.60	20.00	2.56
M SPRING CLIP	2.00	12.06	20.00	19.30

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center  
209 Pandan Gardens  
Singapore 609339  
Tel: 6771 4389  
Fax: 6775 6310  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR XE6348Y

Sembwaste Pte Ltd

30 Hill Street  
#05-04  
Singapore 179360

Home: 68546221Eric

## Vehicle &amp; Document Information

WIP No 59117  
Reg No/Reg Date XE6348Y / 19/03/2021  
Date In/Mileage 39779  
Chassis No W1T964045204859875  
Engine No 470913C0596606  
Make/Model MBCV/Arocs 3236L ENA 8X2/4 515  
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSC00003	Cash	15/11/2022/ 16:28	JAC	610 / Philip Cheong					
					M SPRING CLIP	2.00	12.06	20.00	19.30
					M SPRING CLIP	8.00	2.61	20.00	16.70
					M LOOM TIE	2.00	4.43	20.00	7.09
					M PNEUMATIC SPRING	2.00	31.67	20.00	50.67
					M RIVET SCREW	4.00	7.16	20.00	22.91
					M SPRING CLIP	2.00	0.97	20.00	1.55
					M CLIP	2.00	3.20	20.00	5.12
					M CLIP	2.00	3.20	20.00	5.12
					M CYLINDER SCREW W. FLANGE	14.00	4.08	20.00	45.70
					M COMPANY SIGN	1.00	94.27	20.00	75.42
					M COUPLING PIN	1.00	63.61	20.00	50.89
					M LOCKING LEVER	1.00	36.63	20.00	29.30
					M END CAP	2.00	43.76	20.00	70.02
					M FAN SHROUD	1.00	395.22	20.00	316.18
					M STEP PLATE	1.00	872.96	20.00	698.37
					M ENTRANCE	1.00	631.61	20.00	505.29
					M PANELING, FLAP, OUTER	1.00	1294.10	20.00	1035.28
					M TRIM GRILLE	1.00	1103.54	20.00	882.83
					M CARRIER	1.00	973.90	20.00	779.12
					M BRACKET	1.00	51.80	20.00	41.44
					M LATCH	1.00	48.50	20.00	38.80
					M BRACKET	1.00	51.83	20.00	41.46
					M LATCH	1.00	51.49	20.00	41.19
					M SEAL	1.00	40.56	20.00	32.45
					M COVER	1.00	335.50	20.00	268.40
					M COVER	1.00	335.50	20.00	268.40
					M COVER	1.00	335.50	20.00	268.40
					M COVER	1.00	335.50	20.00	268.40
					M TRIM GRILLE	1.00	53.22	20.00	42.58
					M BRACKET	1.00	16.08	20.00	12.86
					M COVER	1.00	129.93	20.00	103.94
					M COVER	1.00	114.50	20.00	91.60
					M MERCEDES STAR	1.00	137.69	20.00	110.15

Confirmed &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center  
209 Pandan Gardens  
Singapore 609339  
Tel: 6771 4389  
Fax: 6775 6310  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR XE6348Y

Sembwaste Pte Ltd

30 Hill Street  
#05-04  
Singapore 179360

Home: 68546221Eric

## Vehicle &amp; Document Information

WIP No 59117  
Reg No/Reg Date XE6348Y / 19/03/2021  
Date In/Mileage 39779  
Chassis No W1T964045204859875  
Engine No 470913C0596606  
Make/Model MBCV/Arocs 3236L ENA 8X2/4 515  
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	
CSC00003	Cash	15/11/2022/ 16:28	JAC	610 / Philip Cheong	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M IDENTIFICATION PLATE		1.00	47.53	20.00	38.02
M FACING WIPER SYSTEM		1.00	922.72	20.00	738.18
M WIPER ARM		2.00	195.33	20.00	312.53
M IMPLEMENT CARRIER		1.00	1200.30	20.00	960.24
M WIPER ARM		2.00	19.89	20.00	31.82
M SEAL		2.00	5.40	20.00	8.64
M REINFORCEMENT		1.00	30.47	20.00	24.38
M REINFORCEMENT		1.00	30.47	20.00	24.38
M PRESSURE LINE		1.00	336.98	20.00	269.58
M SUCTION LINE		1.00	421.58	20.00	337.26
M REFRIGERANT LINE		1.00	189.71	20.00	151.77
M AIR CONDITIONING SYSTEM		1.00	3190.00	20.00	2552.00
M SEAL		1.00	329.63	20.00	263.70
M AIR INTAKE FITTING		1.00	90.19	20.00	72.15
M NOZZLE, WINDSHIELD WASHER		2.00	22.30	20.00	35.68
M FLAP		1.00	123.93	20.00	99.14
M STEP PLATE		1.00	994.69	20.00	795.75
M BRACKET		1.00	65.22	20.00	52.18
M GRAB HANDLE		1.00	56.70	20.00	45.36
M GRAB HANDLE		1.00	56.70	20.00	45.36
M BRACKET		1.00	130.68	20.00	104.54
M COVER GRILL		1.00	243.21	20.00	194.57
M COVER GRILL		1.00	42.16	20.00	33.73
M BRACKET		1.00	151.16	20.00	120.93
M BUMPER, FRONT		1.00	755.82	20.00	604.66
M BRACKET		1.00	83.75	20.00	67.00
M BRACKET		1.00	83.78	20.00	67.02
M BUMPER, FRONT		1.00	755.82	20.00	604.66
M BUMPER, FRONT		1.00	1103.10	20.00	882.48
M COVER		4.00	4.21	20.00	13.47
M ATTACHMENT ANGLE BRACKET		1.00	57.68	20.00	46.14
M STEP PLATE		1.00	97.26	20.00	77.81
M BRACKET		1.00	188.77	20.00	151.02

Confirmed &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center  
209 Pandan Gardens  
Singapore 609339  
Tel: 6771 4389  
Fax: 6775 6310  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR XE6348Y

Sembwaste Pte Ltd

30 Hill Street  
#05-04  
Singapore 179360

Home: 68546221Eric

## Vehicle &amp; Document Information

WIP No 59117  
Reg No/Reg Date XE6348Y / 19/03/2021  
Date In/Mileage 39779  
Chassis No W1T964045204859875  
Engine No 470913C0596606  
Make/Model MBCV/Arocs 3236L ENA 8X2/4 515  
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSC00003	Cash	15/11/2022/ 16:28	JAC	610 / Philip Cheong					
					M COVER GRILL 180	1.00	84.28	20.00	67.42
					M COVER GRILL 185	1.00	84.25	20.00	67.40
					M COVER GRILL	1.00	66.31	20.00	53.05
					M COVER	1.00	37.01	20.00	29.61
					M COVER	1.00	37.01	20.00	29.61
					M FACING	1.00	78.19	20.00	62.55
					M FACING	1.00	78.19	20.00	62.55
					M BRACKET	1.00	77.25	20.00	61.80
					M BRACKET	1.00	77.25	20.00	61.80
					M FRONT SPOILER	1.00	349.14	20.00	279.31
					M FRONT SPOILER	1.00	325.13	20.00	260.10
					M FACING	1.00	54.60	20.00	43.68
					M FACING	1.00	51.46	20.00	41.17
					M BRACKET	1.00	177.87	20.00	142.30
					M BRACKET	1.00	186.88	20.00	149.50
					M VIBRATION DAMPER	2.00	588.20	20.00	941.12
					M MOUNTING CLIP	4.00	8.64	20.00	27.65
					M CROSSMEMBER	1.00	1697.49	20.00	1357.99
					M CROSSMEMBER	1.00	1368.83	20.00	1095.06
					M [ALT] CONDENSER	1.00	1330.16	20.00	1064.13
					M CHARGE AIR COOLER, AIR	1.00	3450.18	20.00	2760.14
					M RADIAT. PROTECTION GRILLE	1.00	288.51	20.00	230.81
					M COOLANT RADIATOR	1.00	2600.67	20.00	2080.54
					M ENTRANCE	1.00	751.14	20.00	600.91
					M BRACKET	2.00	44.11	20.00	70.58
					M DOWEL	2.00	4.90	20.00	7.84
					M HEXALOBULAR BOLT	4.00	2.83	20.00	9.06
					M HEXALOBULAR BOLT	4.00	2.83	20.00	9.06
					M HEXALOBULAR BOLT	1.00	3.20	20.00	2.56
					M WASHER	2.00	2.64	20.00	4.22
					M TAPPING SCREW	12.00	2.54	20.00	24.38
					M TAPPING SCREW	4.00	2.54	20.00	8.13
					M TAPPING SCREW	4.00	2.17	20.00	6.94

Confirmed &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center  
209 Pandan Gardens  
Singapore 609339  
Tel: 6771 4389  
Fax: 6775 6310  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

**ESTIMATE FOR XE6348Y**

Sembwaste Pte Ltd

30 Hill Street  
#05-04  
Singapore 179360

Home: 68546221Eric

Vehicle & Document Information

WIP No 59117  
Reg No/Reg Date XE6348Y / 19/03/2021  
Date In/Mileage 39779  
Chassis No W1T964045204859875  
Engine No 470913C0596606  
Make/Model MBCV/Arocs 3236L ENA 8X2/4 515  
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	
CSC00003	Cash	15/11/2022/ 16:28	JAC	610 / Philip Cheong	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SPRING LOCK NUT		6.00	4.59	20.00	22.03
M SPRING LOCK NUT		6.00	4.59	20.00	22.03
M SPRING LOCK NUT		2.00	4.59	20.00	7.34
M HEXALOBULAR BOLT		2.00	2.95	20.00	4.72
M HEXALOBULAR BOLT		4.00	2.95	20.00	9.44
M HEXALOBULAR BOLT		2.00	14.01	20.00	22.42
M HEX. HEAD BOLT W. FLANGE		1.00	4.52	20.00	3.62
M CAP BOLT W. HEXAL SOCKET		2.00	3.46	20.00	5.54
M EXPANSION RIVET		2.00	4.18	20.00	6.69
M TAPPING SCREW		2.00	3.20	20.00	5.12
M HEXALOBULAR BOLT		2.00	6.44	20.00	10.30
M HEXALOBULAR BOLT		6.00	1.48	20.00	7.10
M HEXALOBULAR BOLT		4.00	1.48	20.00	4.74
M SCREW		2.00	1.63	20.00	2.61
M NUT-AND-WASHER ASSEMBLY		4.00	3.77	20.00	12.06
M RIVET		4.00	12.60	20.00	40.32
M HEXAGON NUT		2.00	4.12	20.00	6.59
M NUT		1.00	7.70	20.00	6.16
M NUT		8.00	7.70	20.00	49.28
M TAPPING SCREW		2.00	2.14	20.00	3.42
M EXPANSION RIVET		4.00	3.99	20.00	12.77
M EXPANSION RIVET		2.00	3.99	20.00	6.38
M EXPANSION RIVET		4.00	2.42	20.00	7.74
M SPRING LOCK NUT		6.00	1.57	20.00	7.54
M SPRING LOCK NUT		2.00	3.90	20.00	6.24
M HEXALOBULAR BOLT		4.00	3.86	20.00	12.35
M WASHER		3.00	1.57	20.00	3.77
M SCREW		4.00	4.08	20.00	13.06
M SCREW		6.00	4.08	20.00	19.58
M SCREW		3.00	4.08	20.00	9.79
M HEXALOBULAR BOLT		2.00	0.00	00.00	
M HEXALOBULAR BOLT		4.00	0.00	00.00	
M HEXALOBULAR BOLT		4.00	1.23	20.00	3.94

Confirmed &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center  
209 Pandan Gardens  
Singapore 609339  
Tel: 6771 4389  
Fax: 6775 6310  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR XE6348Y

Sembwaste Pte Ltd

30 Hill Street  
#05-04  
Singapore 179360

Home: 68546221Eric

### Vehicle & Document Information

WIP No 59117  
Reg No/Reg Date XE6348Y / 19/03/2021  
Date In/Mileage 39779  
Chassis No W1T964045204859875  
Engine No 470913C0596606  
Make/Model MBCV/Arocs 3236L ENA 8X2/4 515  
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator			
CSC00003	Cash	15/11/2022/ 16:28	JAC	610 / Philip Cheong			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	HEXALOBULAR BOLT			4.00	1.23	20.00	3.94
M	HEXALOBULAR BOLT			2.00	0.00	00.00	
M	HEXALOBULAR BOLT			2.00	0.00	00.00	
M	HEXALOBULAR BOLT			6.00	2.73	20.00	13.10
M	HEXALOBULAR BOLT			2.00	0.00	00.00	
M	HEXALOBULAR BOLT			4.00	13.54	20.00	43.33
M	HEXALOBULAR BOLT			4.00	1.54	20.00	4.93
M	HEXALOBULAR BOLT			7.00	2.39	20.00	13.38

Confirmed & accepted by

Nett 46,237.28  
7% GST on 46237.28 3236.61  
Total Payable 49,473.89

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center  
209 Pandan Gardens  
Singapore 609339  
Tel: 6771 4389  
Fax: 6775 6310  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany