

Name & Address:

ALLIANZ INSURANCE (S) PTE LTD
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Vehicle No:

SFV1339E

Date:

4-May-23

Brand & Model:

MAZDA 6

Franchise:

Mazda

Email/Fax No:

Contact No:

Chassis/VIN No:

JM6GL103200319679

Contact Person (Eurokars)/Wip No:

SHAWN / 53639

Type of Claim:

THIRD PARTY

Policy No:

Date Of Registration:

25/04/2019

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER	MGBVP-50-221ABB	1	A	\$ 1,260.75	\$ 1,260.75
2	TAPE,PROTECTOR	MBCKA-50-EM1	2	A	\$ 9.28	\$ 9.28
3	RETAINER S.S ULTRASONIC CENTER	MK156-67-UC5 64	2	A	\$ 31.54	\$ 31.54
4	SENSOR,ULTRASONIC CENTER	MGMK6-67-UC1 64	2		\$ -	\$ 369.18
5	CORD,SHORT	MGBFT-67-290	1		\$ -	\$ 216.00
6	BRACKER CENTER REAR BUMPER	MDFR5-50-251	1	A	\$ 4.64	\$ 4.64
7	REAR REINFORCEMENT	MGHP9-50-260	1		\$ -	\$ 523.08
8	RETAINER LH REAR	MGHP9-50-2J1A	1		\$ -	\$ 41.73
9	RETAINER RH REAR	MGHP9-50-2H1	1		\$ -	\$ 37.85
10	COVER LH TOWING HOOK REAR	MGSK4-50-EL1 BB	1		\$ -	\$ 61.11
11	COVER RH TOWING HOOK REAR	MGSK4-50-EK1 BB	1		\$ -	\$ 61.11
12	COVER,UNDER-REAR	MGSK4-50-C51	1		\$ -	\$ 115.00
13	RIVET	MTK21-50-355	2	A	\$ 14.84	\$ 14.84
14	FASTENER	MB45A-56-146A	6	A	\$ 14.16	\$ 14.16
15	TAILGATE	MGHY5-62-02X	1	A	\$ 1,441.80	\$ 1,441.80
16	WEATHERSTRIP TAILGATE	MGHP9-62-761A	1		\$ -	\$ 159.14
17	TRIM LOWER TAILGATE	MGHP9-68-960A	1		\$ -	\$ 393.96
18	RECESS TAILGATE	MGHP9-68-966B02	2		\$ -	\$ 27.82
19	CLIP,TRIM	MGJ12-68-865	7	A	\$ 13.02	\$ 13.02
20	FASTENER	MGJ21-68-885B02	4	A	\$ 9.44	\$ 9.44
21	VALVE,ONEWAY	MGHP9-58-867	2		\$ -	\$ 24.12
22	LOCK TAILGATE	MG33M-62-310B	1		\$ -	\$ 289.78
23	FASTENER	MKD51-51-W24	12	A	\$ 77.88	\$ 77.88
24	FASTENER	MD201-51-146	3	A	\$ 7.08	\$ 7.08
25	GROMMET	MS47P-51-141	2	A	\$ 6.24	\$ 6.24
26	LAMP RH TAILGATE	MG45H-51-3F0A	1		\$ -	\$ 827.86
27	GASKET LH LAMP TAILGATE	MG45H-51-3J8	1	A	\$ 29.76	\$ 29.76
28	GASKET RH LAMP TAILGATE	MG45H-51-3H8	1	A	\$ 29.76	\$ 29.76
29	TAIL LAMP RH	MGJE8-51-150B	1		\$ -	\$ 1,655.54
30	GASKET RH TAIL LAMP	MGJE8-51-153	1	A	\$ 29.76	\$ 29.76
31	GASKET LH TAIL LAMP	MGJE8-51-163	1	A	\$ 29.76	\$ 29.76
32	FASTENER	MKD53-51-146B	2	A	\$ 7.42	\$ 7.42

33	FASTENER	MGHP9-51-146	2	A	\$	4.72	\$	4.72
34	FASTENER,LAMP	MGJ6A-51-14Y	2	A	\$	29.68	\$	29.68
35	ORNAMENT MAZDA	MGHP9-51-711	1	A	\$	30.85	\$	30.85
36	ORNAMENT 6	MGHP9-51-721	1	A	\$	27.90	\$	27.90
37	ORNAMENT SKYACTIV	MGHP9-51-771	1	A	\$	80.41	\$	80.41
38	MASCOT REAR	MGHR1-51-731	1	A	\$	47.29	\$	47.29
39	FASTENER WS	MC513-50-896	2	A	\$	14.84	\$	14.84
40	FASTENER WS	MD204-50-896A	2	A	\$	4.72	\$	4.72
41	PIN,STUD WS	MG21E-63-938B	1	A	\$	10.20	\$	10.20
42	SPACER WS	MGJ6A-50-897	1	A	\$	11.13	\$	11.13
43	REAR END PANEL	MGHY9-70-75ZA	1		\$	-	\$	706.57
44	TRIM REAR END PANEL	MGJV4-68-89XA02	1		\$	-	\$	449.16
45	COVER TRIM REAR END PANEL	MGHP9-68-894A02	1		\$	-	\$	53.95

Sub-Total (Parts Price) \$ **3,278.87** \$ 9,291.83

LABOUR / SERVICES CHARGES								
NO	DESCRIPTION			REVISED		PRICE		
1	TO REPLACE REAR BUMPER , REAR END PANEL AND TAILGATE.			\$	1,320.00	\$	4,000.00	
2	TO RESPRAY REAR BUMPER , REAR END PANEL AND TAILGATE.			\$	1,260.00	\$	2,600.00	
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.			\$	-	\$	180.00	
4	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			\$	560.00	\$	560.00	
5	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.			\$	120.00	\$	120.00	
6	TO TRANSFER / REPLACE REVERSE SENSOR.			\$	250.00	\$	660.00	
7	TO SUPPLY 1PC REAR NUMBER PLATE WITH CASING.			\$	-	\$	70.00	
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$	180.00	\$	250.00	
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$	250.00	\$	300.00	
10	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU).			\$	150.00	\$	250.00	
11	SUNDRIES.			\$	20.00	\$	50.00	

Survey Date & Time: 25/11/22	Repair Days: 5	Excess:
------------------------------	----------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ **4,110.00** \$ 9,040.00

		REVISED		PRICE	
Parts Price	\$	3,278.87	\$	9,291.83	
Labour Price	\$	4,110.00	\$	9,040.00	
Total (Initial Estimate)	\$	7,388.87	\$	18,331.83	
Supp 1	\$	-	\$	-	
Supp 2	\$	-	\$	-	
Supp 3	\$	-	\$	-	
Total (Before Excess)	\$	7,388.87	\$	18,331.83	
Less Excess	\$	-	\$	-	
TOTAL (After Excess)	\$	7,388.87	\$	18,331.83	
GST 7%	\$	517.22	\$	1,283.23	
GRAND TOTAL	\$	7,906.09	\$	19,615.06	