

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MS. HAN HWEE TOO

BLK 310 TAMPINES ST 32 #10-130

SINGAPORE 520310

TAX INVOICE 7PAXA.

Repair Code : CLM15732

Date in : 19/11/2022

Vehicle Num. : SDP1970L

Model : TOYOTA COROLLA ALTIS 1.6L CVT

Chassis/Eng# : MR053REH104546613/1ZRX556058

xiao tong

Contact : 97527226, 98898776

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Buelced</i>	1	781.10	✓ 781.10
REAR BOOTLID 'ALTIS' EMBLEM	1	54.10	✓ 54.10
REAR BOOTLID 'COROLLA' EMBLEM <i>new</i>	1	50.20	✓ 50.20
REAR BOOTLID 'LOGO' EMBLEM	1	58.50	✓ 58.50
REAR BOOTLID HINGES L/R <i>new</i>	2	79.60	+ 159.20
REAR BOOTLID INNER TRIM GARNISH <i>new</i>	1	181.85	+ 181.85
REAR BOOTLID LOCK STRIKER <i>new</i>	1	85.00	+ 85.00
REAR BOOTLID LOCK STRIKER COVER <i>new</i>	1	42.00	+ 42.00
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	379.20	✓ 379.20
REAR BOOTLID REFLECTOR GASKET SEAL L/R <i>new</i>	2	43.10	+ 86.20
REAR BOOTLID REFLECTOR L/R <i>new</i>	2	374.45	+ 748.90
REAR BOOTLID RUBBER GUIDE STOPPER <i>new</i>	4	6.80	+ 27.20
REAR BOOTLID WEATHER STRIP <i>new</i>	1	271.45	✓ 271.45
REAR BUMPER <i>Dehd</i>	1	556.40	✓ 556.40
REAR BUMPER END SEAL COVER L/R <i>new</i>	2	55.10	+ 110.20
REAR BUMPER REFLECTOR L/R <i>new</i>	2	59.80	✓ 119.60
REAR BUMPER REINFORCEMENT <i>Dehd</i>	1	398.70	✓ 398.70
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Dehd</i>	2	68.20	✓ 136.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MS. HAN HWEE TOO
 BLK 310 TAMPINES ST 32 #10-130
 SINGAPORE 520310

Contact : 97527226 , 98898776

TAX INVOICE

Repair Code : CLM15732

Date in : 19/11/2022

Vehicle Num. : SDP1970L

Model : TOYOTA COROLLA ALTIS 1.6L CVT

Chassis/Eng# : MR053REH104546613/1ZRX556058

REAR BUMPER REVERSE SENSOR	<i>Dented</i>	2	198.00	✓	396.00
REAR BUMPER REVERSE SENSOR HOLDER	<i>m</i>	2	43.00	✓	86.00
REAR BUMPER SIDE RETAINER L/R	<i>next m</i>	2	109.30	f	218.60
REAR END PANEL	<i>Dented</i>	1	670.00	✓	670.00
REAR END PANEL INNER TOP GARNISH	<i>Dented</i>	1	241.90	✓	241.90
REAR END PANEL KEYLESS SENSOR	<i>Dented</i>	1	168.00	✓	168.00
REAR FENDER INNER TRIM L/R	<i>next m</i>	2	338.00	+	676.00
REAR FLOOR PANEL TOP BOARD COVER	<i>Dented</i>	1	267.00	✓	267.00
REAR SPARE TYRE PANEL FASTENER LOCK	<i>next Bent</i>	1	28.40	✓	28.40
REAR TAILLAMP INNER BLACK RUBBER GASKET	<i>rec</i>	2	25.50	✓	51.00
REAR TAILLAMP L/R	<i>crushed</i>	2	391.90	✓	783.80
REAR TAILLAMP LOWER BRACKET L/R	<i>crushed</i>	2	88.70	✓	177.40
Subtotal before discount					8,010.30
Percentage discount 25%					2,002.58
Sub-total 1					6,007.73
REAR BOOTLID CHROME MOULDING CLIPS - SET	<i>next m</i>	1	30.00	+	30.00
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET	<i>next m</i>	1	50.00	+	50.00
REAR BUMPER CLIPS - SET	<i>m</i>	1	50.00	30	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MS. HAN HWEE TOO
BLK 310 TAMPINES ST 32 #10-130
SINGAPORE 520310

Contact : 97527226 , 98898776

TAX INVOICE

Repair Code : CLM15732

Date in : 19/11/2022

Vehicle Num. : SDP1970L

Model : TOYOTA COROLLA ALTIS 1.6L CVT

Chassis/Eng# : MR053REH104546613/1ZRX556058

REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	20.00	<i>10</i>	20.00
REAR FENDER INNER TRIM CLIPS L/R - SET <i>new</i>	2	40.00	<i>+</i>	80.00
REAR NUMBER PLATE <i>2 new</i>	1	25.00	<i>40</i>	25.00
REAR NUMBER PLATE HOLDER	1	50.00	<i>+</i>	50.00
Subtotal before discount				305.00
Percentage discount 0%				0.00
Sub-total 2				305.00
Parts-total				6,312.73

LABOUR

To transfer rear bootlid mechanism lock outer handle reflector

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

60 ~~80.00~~

✓ 80.00

60 100.00

(200) 1,300.00

2060 *800* 1,000.00

60 100.00

2,660.00

8,972.73

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/S 23/11/22
06 days

total: 6356.36

L/S: SK ✓