

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

LEW SAN LENG
 BLK 124B RIVERVALE DRIVE #04-211
 SINGAPORE 542124

Contact : 93738883

TAX INVOICE

Repair Code : CLM15734 TP China
 Date in : 21/11/2022 Veron
 Vehicle Num. : SJA3420C
 Model : TOYOTA ESTIMA 2.4G A
 Chassis/Eng# : ACR500054804/2AZF094799

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	546.00	546.00
REAR BUMPER REFLECTOR L/R <i>included</i>	2	56.00	112.00
REAR BUMPER SIDE CORNER RETAINER L/R <i>new</i>	2	45.00	90.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	87.00	174.00
REAR BUMPER TOW HOOK COVER L/R <i>new</i>	2	25.00	50.00
REAR END PANEL <i>Dented</i>	1	520.00	520.00
REAR END PANEL ANTENNA SENSOR <i>Dented</i>	1	107.00	107.00
REAR END PANEL INNER LOWER GARNISH	1	175.00	175.00
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	225.00	225.00
REAR FENDER INNER TRIM BOARD L/R <i>Dented RH Dented</i>	2	745.00	1490.00
REAR FLOOR HORIZONTAL PANEL <i>Repair</i>	1	290.00	290.00
REAR FLOOR PANEL <i>Repair</i>	1	780.00	780.00
REAR FLOOR PANEL TOP BOARD COVER <i>Dented</i>	1	780.00	780.00
REAR FLOOR PANEL TRIM LINER CARPET <i>new</i>	1	680.00	680.00
REAR TAILGATE <i>Dented</i>	1	1855.00	1855.00
REAR TAILGATE 'ESTIMA' EMBLEM <i>2</i>	1	57.00	57.00
REAR TAILGATE 'G' EMBLEM <i>new</i>	1	57.00	57.00
REAR TAILGATE 'LOGO' EMBLEM	1	61.00	61.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

LEW SAN LENG
 BLK 124B RIVERVALE DRIVE #04-211
 SINGAPORE 542124

Contact : 93738883

TAX INVOICE

Repair Code : CLM15734

Date in : 21/11/2022

Vehicle Num. : SJA3420C

Model : TOYOTA ESTIMA 2.4G A

Chassis/Eng# : ACR500054804/2AZF094799

REAR TAILGATE HINGES L/R	2	67.00	+ 134.00
REAR TAILGATE INNER PULL HANDLE	1	55.00	+ 55.00
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	2	19.00	+ 38.00
REAR TAILGATE INNER TRIM BOARD	1	467.00	✓ 467.00
REAR TAILGATE LOCK STRIKER	1	25.00	+ 25.00
REAR TAILGATE MECHANISM LOCK	1	391.00	✓ 391.00
REAR TAILGATE MECHANISM LOCK GARNISH	1	38.00	✓ 38.00
REAR TAILGATE WEATHER STRIP	1	356.00	✓ 356.00
REAR TAILGATE WINDSCREEN MOULDING	1	205.00	✓ 205.00
Subtotal before discount			9,758.00
Percentage discount 25%			2,439.50
Sub-total 1			7,318.50
REAR BUMPER CLIPS - SET	1	80.00	30 80.00
REAR BUMPER REVERSE SENSOR - SET	1	280.00	20 280.00
REAR BUMPER TOP CHROME PLATE	1	280.00	20 280.00
REAR END PANEL INNER LOWER GARNISH CLIPS - SET	1	40.00	20 40.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	40.00	20 40.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	50.00	30 100.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

LEW SAN LENG
 BLK 124B RIVERVALE DRIVE #04-211
 SINGAPORE 542124

Contact : 93738883

TAX INVOICE

Repair Code : CLM15734
 Date in : 21/11/2022
 Vehicle Num. : SJA3420C
 Model : TOYOTA ESTIMA 2.4G A
 Chassis/Eng# : ACR500054804/2AZF094799

REAR FLOOR PANEL INSULATOR MAT	1	300.00	+	300.00
REAR FLOOR PANEL TRIM LINER CARPET CLIPS - SET	1	50.00	+	50.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	60.00	30	60.00
REAR TAILGATE NUMBER PLATE	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	+	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	30.00	+	30.00
REAR TAILGATE STICKER	1	150.00	80	150.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60	80.00
Subtotal before discount				1,565.00
Percentage discount 0%				0.00
Sub-total 2				1,565.00
Parts-total				8,883.50

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	80 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	80 1,200.00
To apply anti-rust chemical on repaired and replaced panel.	60 120.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LEW SAN LENG
BLK 124B RIVERVALE DRIVE #04-211
SINGAPORE 542124

Contact : 93738883

TAX INVOICE

Repair Code : CLM15734

Date in : 21/11/2022

Vehicle Num. : SJA3420C

Model : TOYOTA ESTIMA 2.4G A

Chassis/Eng# : ACR500054804/2AZF094799

To remove, reinstall tailgate mechanism and check for function

	60	80.00
Labour Total	1980	2,730.00
Parts & Labour Total		11,613.50

*** This is a computer-generated document which requires no signature.***

page 4

Adrian G
H/S 22/11/22

06 Days

Whl: 7542.25

C/S: 611 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: