

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **GBB 4838P**

Made : Toyota

Model : Hiace Manual

Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear Bumper	1	\$ 491.60	\$ 491.60	crn -
2	Rear Bumper Lower Bracket	4	\$ 28.20	\$ 112.80	X NN
3	Rear Bumper Side Retainer RH	1	\$ 25.30	\$ 25.30	X NN
4	Rear Bumper Side Retainer LH	1	\$ 25.30	\$ 25.30	crn -
5	Rear End Panel Inner	1	\$ 1,198.20	\$ 1,198.20	X NN
6	Rear End Panel Outer	1	\$ 371.40	\$ 371.40	X NN
7	Rear End Panel Top Garnish	1	\$ 165.00	\$ 165.00	X NN
8	Rear End Panel Side LH	1	\$ 362.10	\$ 362.10	Scr - nn
9	Rear Floor Panel Mat	1	\$ 796.00	\$ 796.00	X nn
10	Rear Floor Panel	1	\$ 1,960.00	\$ 1,960.00	X nn
11	Rear Tailgate	1	\$ 2,337.90	\$ 2,337.90	dent R
12	Rear Tailgate Windscreen Glass	1	\$ 1,451.30	\$ 1,451.30	X nn
13	Rear Tailgate Emblem	1	\$ 72.20	\$ 72.20	vel -
14	Rear Tailgate Inner Cardboard	1	\$ 196.00	\$ 196.00	X
15	Rear Tailgate Inner Center Locking Control	1	\$ 264.00	\$ 264.00	X
16	Rear Tailgate Mechanism Lock	1	\$ 299.60	\$ 299.60	X
17	Rear Tailgate Mechanism Lock Striker	1	\$ 55.00	\$ 55.00	X
18	Rear Tailgate Outer Garnish	1	\$ 298.00	\$ 298.00	X
19	Rear Tailgate Rubber Guide Stopper	2	\$ 41.80	\$ 83.60	X } NN
20	Rear Tailgate Rubber Cap	2	\$ 19.30	\$ 38.60	X
21	Rear Tailgate Weatherstrip	1	\$ 442.00	\$ 442.00	X
22	Rear Tailgate Weatherstrip Protector	1	\$ 217.00	\$ 217.00	X
23	Rear Taillamp Assembly RH	1	\$ 354.80	\$ 354.80	X
24	Rear Taillamp Assembly LH	1	\$ 354.80	\$ 354.80	crn -
25	Rear Taillamp Lower Garnish RH	1	\$ 170.00	\$ 170.00	X NN
26	Rear Taillamp Lower Garnish LH	1	\$ 170.00	\$ 170.00	nn
27	Rear Taillamp Lower Garnish Retainer RH	1	\$ 60.00	\$ 60.00	X NN
28	Rear Taillamp Lower Garnish Retainer LH	1	\$ 60.00	\$ 60.00	crn -
29	Rear Taillamp Panel LH	1	\$ 300.00	\$ 300.00	X NN
30	Rear Side Panel Outer LH	1	\$ 2,194.90	\$ 2,194.90	buc -
31	Rear Side Panel Inner LH	1	\$ 1,070.20	\$ 1,070.20	X NN
32	Rear Side Lower Corner Inner Panel LH	1	\$ 187.50	\$ 187.50	cut - X R

2724

25% - 681

33	Rear Side Panel Inner Trim Board LH	1	\$ 198.40	\$ 198.40	X
34	Rear Side Inner Lower Panel LH	1	\$ 1,140.40	\$ 1,140.40	X
35	Rear Side Panel Air Vent LH	1	\$ 86.30	\$ 86.30	X
36	Rear Side Railway End Garnish LH	1	\$ 47.30	\$ 47.30	X
37	Rear Side Railway LH	1	\$ 864.10	\$ 864.10	X
38	Rear Wheel Cap LH	1	\$ 179.30	\$ 179.30	X
39	Rear Wheel Rim LH	1	\$ 260.00	\$ 260.00	X
40	Rear Wheel Hub Bearing LH	1	\$ 187.00	\$ 187.00	X
41	Rear Wheel Hub LH	1	\$ 390.00	\$ 390.00	X
42	Rear Shock Absorber LH	1	\$ 439.00	\$ 439.00	X
43	Rear Axle	1	\$ 1,984.10	\$ 1,984.10	X
Parts Sub Total :				\$ 21,961.00	
25% Discount				\$ 5,490.25	
PARTS TOTAL :				\$ 16,470.75	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Rear Number Plate	1	\$ 50.00	\$ 50.00	X nn
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 50.00	X ncc
3	Rear Taillamp Clips - Set	1	\$ 50.00	\$ 50.00	X
4	Rear Taillamp Lower Garnish Clips - Set	1	\$ 50.00	\$ 50.00	X
5	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ 50.00	X nn
6	Rear Tailgate Outer Garnish Clips - Set	1	\$ 30.00	\$ 30.00	X
7	Rear Tailgate Inner Board Clips - Set	1	\$ 50.00	\$ 50.00	X
8	Rear Tailgate Windscreen Glass Sealant	1	\$ 150.00	\$ 150.00	X
9	Rear Tailgate "70km/h" Sticker	1	\$ 50.00	\$ 50.00	X ncc 30
10	Rear Tailgate "8 Pax" Sticker	1	\$ 50.00	\$ 50.00	X ncc 30
11	Rear Tailgate Sealant	1	\$ 150.00	\$ 150.00	X
12	Rear End Panel Sealant	1	\$ 150.00	\$ 150.00	X
13	Rear Side Panel Outer Sealant	1	\$ 150.00	\$ 150.00	X
14	Rear Side Panel Inner Sealant	1	\$ 150.00	\$ 150.00	X nn
15	Rear Side Lower Panel Sealant	1	\$ 150.00	\$ 150.00	X
16	Rear Side Panel Inner Trim Board Clips - Set	1	\$ 50.00	\$ 50.00	X
17	Rear Tyre LH	1	\$ 350.00	\$ 350.00	X
18	Rear Bumper Reverse Sensor - Set	1	\$ 250.00	\$ 250.00	X
19	Rear Tailgate Reverse Camera	1	\$ 500.00	\$ 500.00	X
SPECIAL NETT TOTAL :				\$ 2,480.00	

Nos.	LABOUR	TOTAL S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 2,100.00	200
2	To Spray Paint Affected Areas	\$ 1,800.00	600
3	Wiring & Bulb Check	\$ 100.00	30
4	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 150.00	X
5	To Transfer Rear Tailgate Mechanism	\$ 150.00	X
6	To Remove & Refix Rear Tailgate Reverse Camera	\$ 150.00	X
7	To Remove & Refix Rear Bumper Reverse Sensor	\$ 120.00	X

8	To Remove & Refix Rear Exhaust Pipe to facilitate repairs	\$	150.00	X
9	To Remove & Refix Interior Upholstry to facilitate repairs	\$	200.00	X
10	To Remove & Refix Rear Undercarriage	\$	550.00	X
11	To Remove & Refix Rear Tyre and Conduct Wheel Balancing	\$	150.00	X
12	To Conduct Four Wheel Alignment	\$	150.00	X
13	To apply anti rust on affected parts	\$	150.00	X
14	To Conduct Water Leak Test	\$	100.00	X
15	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$	480.00	X
LABOUR TOTAL :		\$	6,500.00	

PARTS TOTAL : \$ 16,470.75

SPECIAL NETT TOTAL : \$ 2,480.00

LABOUR TOTAL : \$ 6,500.00

GRAND TOTAL : \$ 25,450.75

Infm 90047659

24/11/22 bpm

5 days
After paint
L/S.

Total P = 2043

Total = 3583

20% = 716

= 2867

Final = 2850 //

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: