

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011757/AQP3Q2**Date:** 29/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00262362100		
Claimant Vehicle No :	SJB6066S	Insured Vehicle No :	EW8939J		
Date of Loss:	19/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208339/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB6066S	Engine No:	K20A5820130
Make & Model:	HONDA CIVIC, 2.0 TYPE-R (M)	Chassis No:	FD21400130
Reg. Date:	03/12/2007 (Man. Year: 2007)	Odometer:	234501 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,983.92	2,468.40	12,515.52	83.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	1,910.00	4,070.00	68.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,963.92	4,378.40	16,585.52	79.11
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	20,963.92	3,500.00	17,463.92	83.30

INSPECTION

Date of Assignment:	30/11/2022	
Date Inspected:	16/01/2023 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2023)
Parts:	144	HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB6066S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR SIDE MIRROR RH	Damaged	1,642.30 FL	*992.00 FL
2	1		*FRONT DOOR RH	Repair	1,694.80 FL	*- FL
3	1		*FRONT DOOR PROTECTOR GARNISH RH	Repair	277.60 FL	*- FL
4	1		*FRONT DOOR TOP MOULDING	Not Necessary	134.60 FL	*- FL
5	1		*FRONT DOOR INNER TRIM RH	Not Necessary	498.10 FL	*- FL
6	1		*FRONT DOOR INNER LOCK RH	Not Necessary	299.10 FL	*- FL
7	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	137.20 FL	*- FL
8	1		*FRONT DOOR OUTER STRIP RH	Repair	120.10 FL	*- FL
9	1		*FRONT DOOR LOWER INNER RUBBER RH	Not Necessary	59.60 FL	*- FL
10	1		*FRONT DOOR POWER WINDOW MOTOR C/W REGULATOR RH	Not Necessary	399.40 FL	*- FL
11	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	72.80 FL	*- FL
12	1		*ROCKER PANEL RH (OUTER)	Repair	363.70 FL	*- FL
13	1		*SET SIDE SKIRT	Deformed	1,238.40 FS	*800.00 FS
14	1		*REAR DOOR RH	Dented	798.90 FL	*798.90 FL
15	1		*REAR DOOR PROTECTOR GARNISH	Deformed	257.10 FL	*257.10 FL
16	2		*REAR DOOR LOWER RUBBER RH	Not Necessary	111.40 FL	*- FL
17	1		*REAR DOOR HINGE RH	Not Necessary	52.70 FL	*- FL
18	1		*REAR DOOR CHECKER RH	Not Necessary	98.40 FL	*- FL
19	1		*REAR DOOR INNER LOCK RH	Not Necessary	234.60 FL	*- FL
20	1		*REAR DOOR LOCK CATCHER RH	Not Necessary	25.40 FL	*- FL
21	1		*REAR DOOR INNER TRIM RH	Not Necessary	864.20 FL	*- FL
22	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	118.60 FL	*- FL
23	1		*REAR DOOR POWER WINDOW MOTOR C/W REGULATOR RH	Not Necessary	341.70 FL	*- FL
24	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	65.80 FL	*- FL
25	1		*REAR DOOR OUTER STRIP RH	Not Necessary	108.70 FL	*- FL
26	1		*REAR DOOR FRAME WEATHER STRIP RH	Not Necessary	155.80 FL	*- FL
27	1		*REAR FENDER RH	Repair	798.20 FL	*- FL
28	1		*REAR FENDER COWLING RH	Not Necessary	172.20 FL	*- FL
29	1		*REAR WINDSCREEN MOULDING	Not Necessary	156.70 FL	*- FL
30	1		*REAR LOWER ARM RH	Not Necessary	398.30 FL	*- FL
31	1		*REAR UPPER ARM RH	Not Necessary	298.50 FL	*- FL
32	1		*REAR SWING ARM RH	Not Necessary	316.40 FL	*- FL
33	1		*REAR SHOCK ABSORBER RH	Not Necessary	488.20 FL	*- FL
34	1		*REAR LINKAGE RH	Not Necessary	110.50 FL	*- FL
35	1		*REAR WHEEL HUP C/W BEARING RH	Not Necessary	489.20 FL	*- FL
36	1		*REAR KNUCKLE ARM RH	Not Necessary	582.40 FL	*- FL
37	1		*REAR ABS SENSOR RH	Not Necessary	298.80 FL	*- FL
38	1		*REAR BUMPER	Repair	946.20 FL	*- FL
39	1		*REAR BUMPER SIDE RETAINER	Not Necessary	156.20 FL	*- FL
40	1		*SET SIDE SKIRT CLIP	Necessary	80.00 FS	*30.00 FS
41	1		*REAR FENDER SEALANT RH	Not Necessary	150.00 FS	*- FS
42	1		*REAR FENDER COWLING CLIP RH	Not Necessary	60.00 FS	*- FS
43	1		*REAR WINDSCREEN SEALANT	Not Necessary	180.00 FS	*- FS
44	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
45	1		*REAR WHEEL TYRE RH	Not Necessary	800.00 FS	*- FS
46	1		*REAR WHEEL RIM RH	Not Necessary	850.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
48	1		*SET REAR BUMPER CLIP	Not Necessary	80.00 FS	*- FS
49	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	17,812.80 2,878.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,828.88 409.60
					Total Parts (\$\$)	14,983.92 2,468.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,200.00
3	WIRING CHECK	New	250.00	30.00
4	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
5	TRANFER FRONT DOOR MECHANISM	New	80.00	0.00
6	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
7	FOUR WHEEL ALIGNMENT	New	120.00	0.00
8	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
9	TRANFER REAR DOOR MECHANISM	New	80.00	80.00
10	REMOVE & REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	0.00
11	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
12	RESET ABS LIGHT	New	350.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,980.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >