

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 16.01.2023

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SJB6066S
MODEL : HONDA CIVIC TYPE-R
DATE OF ACCIDENT : 19.11.2022
TIME OF ACCIDENT : 13:00 HRS

Xiao Chen
FD21400130

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR SIDE MIRROR RH <i>Repl</i>	1	\$ 1,642.30	\$ 1,642.30
2	FRONT DOOR RH <i>Repl</i>	1	\$ 1,694.80	\$ 1,694.80
3	FRONT DOOR PROTECTOR GARNISH RH <i>Repl</i>	1	\$ 277.60	\$ 277.60
4	FRONT DOOR TOP MOULDING <i>2</i>	1	\$ 134.60	\$ 134.60
5	FRONT DOOR INNER TRIM RH <i>2</i>	1	\$ 498.10	\$ 498.10
6	FRONT DOOR INNER LOCK RH <i>2</i>	1	\$ 299.10	\$ 299.10
7	FRONT DOOR WEATHER STRIP RH <i>2</i>	1	\$ 137.20	\$ 137.20
8	FRONT DOOR OUTER STRIP RH <i>2</i>	1	\$ 120.10	\$ 120.10
9	FRONT DOOR LOWER INNER RUBBER RH <i>not a</i>	1	\$ 59.60	\$ 59.60
10	FRONT DOOR POWER WINDOW MOTOR C/W REGULATOR RH <i>not a</i>	1	\$ 399.40	\$ 399.40
11	FRONT DOOR GLASS CHANNEL RH <i>new</i>	1	\$ 72.80	\$ 72.80
12	ROCKER PANEL RH (OUTER) <i>Repl</i>	1	\$ 363.70	\$ 363.70
13	SIDE SKIRT (SET) <i>del</i>	1	\$ 1,548.00	\$ 1,548.00
14	REAR DOOR RH <i>del</i>	1	\$ 798.90	\$ 798.90
15	REAR DOOR PROTECTOR GARNISH <i>del</i>	1	\$ 257.10	\$ 257.10
16	REAR DOOR LOWER RUBBER RH <i>2</i>	2	\$ 55.70	\$ 111.40
17	REAR DOOR HINGE RH <i>2</i>	1	\$ 52.70	\$ 52.70
18	REAR DOOR CHECKER RH <i>2</i>	1	\$ 98.40	\$ 98.40
19	REAR DOOR INNER LOCK RH <i>2</i>	1	\$ 234.60	\$ 234.60

992

800 (sn)

TO : CHINA TAIPIING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJB6066S
 MODEL : HONDA CIVIC TYPE-R
 DATE OF ACCIDENT : 19.11.2022
 TIME OF ACCIDENT : 13:00 HRS

20	REAR DOOR LOCK CATCHER RH	1	\$ 25.40	\$ 25.40	x
21	REAR DOOR INNER TRIM RH	1	\$ 864.20	\$ 864.20	x
22	REAR DOOR WEATHER STRIP RH	1	\$ 118.60	\$ 118.60	x
23	REAR DOOR POWER WINDOW MOTOR C/W REGULATOR RH	1	\$ 341.70	\$ 341.70	x
24	REAR DOOR GLASS CHANNEL RH	1	\$ 65.80	\$ 65.80	x
25	REAR DOOR OUTER STRIP RH	1	\$ 108.70	\$ 108.70	x
26	REAR DOOR FRAME WEATHER STRIP RH	1	\$ 155.80	\$ 155.80	x
27	REAR FENDER RH	1	\$ 798.20	\$ 798.20	x
28	REAR FENDER COWLING RH	1	\$ 172.20	\$ 172.20	x
29	REAR WINDSCREEN MOULDING	1	\$ 156.70	\$ 156.70	x
30	REAR LOWER ARM RH	1	\$ 398.30	\$ 398.30	x
31	REAR UPPER ARM RH	1	\$ 298.50	\$ 298.50	x
32	REAR SWING ARM RH	1	\$ 316.40	\$ 316.40	x
33	REAR SHOCK ABSORBER RH	1	\$ 488.20	\$ 488.20	x
34	REAR LINKAGE RH	1	\$ 110.50	\$ 110.50	x
35	REAR WHEEL HUP C/W BEARING RH	1	\$ 489.20	\$ 489.20	x
36	REAR KNUCKLE ARM RH	1	\$ 582.40	\$ 582.40	x
37	REAR ABS SENSOR RH	1	\$ 298.80	\$ 298.80	x
38	REAR BUMPER	1	\$ 946.20	\$ 946.20	x
39	REAR BUMPER SIDE RETAINER	1	\$ 156.20	\$ 156.20	x

2048

1638.40

S-N: 800

TOTAL PRICE \$ 15,692.40
 LESS 20% \$ 3,138.48
SUB TOTAL PRICE \$ 12,553.92

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	SIDE SKIRT CLIP (SET)	1	\$ 80.00	\$ 80.00	30
2	REAR FENDER SEALANT RH	1	\$ 150.00	\$ 150.00	x
3	REAR FENDER COWLING CLIP RH	1	\$ 60.00	\$ 60.00	x
4	REAR WINDSCREEN SEALANT	1	\$ 180.00	\$ 180.00	x
5	REAR WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00	x
6	REAR WHEEL TYRE RH	1	\$ 800.00	\$ 800.00	x
7	REAR WHEEL RIM RH	1	\$ 850.00	\$ 850.00	x
8	WHEEL CAP (SET)	1	\$ 120.00	\$ 120.00	x

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJB6066S
 MODEL : HONDA CIVIC TYPE-R
 DATE OF ACCIDENT : 19.11.2022
 TIME OF ACCIDENT : 13:00 HRS

9	REAR BUMPER CLIP (SET) } NP	1	\$ 80.00	\$ 80.00	x
10	BRAKE OIL } NW	1	\$ 30.00	\$ 30.00	+

30

TOTAL \$ 2,430.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	1200.
3	WIRING CHECK	\$ 250.00	30
4	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	X
5	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	X
6	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	X
7	FOUR WHEEL ALIGNMENT	\$ 120.00	X
8	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	X
9	TRANSFER REAR DOOR MECHANISM	\$ 80.00	✓
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	X
11	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
12	RESET ABS LIGHT	\$ 350.00	X

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SJB6066S
MODEL : HONDA CIVIC TYPE-R
DATE OF ACCIDENT : 19.11.2022
TIME OF ACCIDENT : 13:00 HRS

13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 5,980.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,983.92
TOTAL LABOUR COST : \$ 5,980.00
TOTAL REPAIR COST : \$ 20,963.92

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Total: 4378.40

L/s 3.5K.

3.5K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: