

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 21 Dec 2022

## **Preliminary Advice**

Insured Vehicle No : XE2046U  
TP Vehicle No : GBB7372X  
Make : HYUNDAI H-1 STAREX  
Date of Inspection : 23/11/2022  
Inspection At : BIFROST AUTO PTE LTD (KAKI BUKIT)  
8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT  
SINGAPORE 415875

Accident Date : 19/11/2022  
Assignment Date : 30/11/2022  
Est. Duration of Repair : 5

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,495.20
Revised Amount	:S\$	7,414.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,414.40
Lump Sum Repair	:S\$	5,700.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.