

Huey Yon (LKKAuto)

From: Huey Yon (LKKAuto)
Sent: Monday, 19 December 2022 3:51 PM
To: Claims Dept
Cc: SUR
Subject: RE: TP GBB 7372X / SNM22D208347/C02/TANKL / DOA: 19/11/2022

Dear Cristina,

Without prejudice

We will be advising our principal a cost of repair of LS \$5,700.00 with 5 days of repair, subject to their approval.

Best Regards,

Huey Yon | case handler
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

From: Claims Dept <claims_rar@bifrostauto.com>
Sent: Monday, 19 December 2022 10:58 AM
To: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Irfan (LKK Auto) <irfan@lkkauto.com>
Subject: Re: TP GBB 7372X / SNM22D208347/C02/TANKL / DOA: 19/11/2022

WITHOUT PREJUDICE

Dear Huey Yon,

Please consider closing at \$5931.52/- 5 days for vehicle no GBB 7372 X.

Below are the part numbers we used for list price reference, which came directly from Hyundai
66400-4H011 (bonnet) - **\$1182** (instead of \$900)
92102-4H030 (headlamp) - **\$635** (instead of \$320)

Your consideration and assistance is highly appreciated!

Thank you!

The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document.

Regards,
Cristina
Motor Claims Department
BIFROST AUTO PTE. LTD