

ESTIMATE OF REPAIR

Veh# : SNF5803U

Model: MERC CLA180
31/3/2010-31/10/2029

Accident Date : 23/11/22

3P: GBL8303L (AIG)

Location : BKE (PIE) BEFORE KJE EXIT

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper (BODY KIT) <i>Distorted</i>		2400.00	1600 (SN).
2	10 pcs	Rear bumper clips <i>NE</i>		30.00	✓
3	1 pc	Rear bumper enforcement <i>Dented</i>	780.00	✓	
4	4 pcs	Rear bumper reverse sensor <i>2 pieces damaged</i>	936.00	468	
5	4 pcs	Rear bumper reverse sensor wire <i>NEC</i>	247.00	✓	
6	2 pcs	Rear bumper bracket (Lower) <i>2nd</i>	178.00	✓	
7	2 pcs	Rear bumper retainer <i>NE</i>	262.50	✓	
8	2 pcs	Rear bumper o/s & n/s retainer <i>NE</i>	226.50	✓	
9	1 pc	Rear end panel outer <i>Dented</i>	1300.40	✓	980
10	2 pcs	Rear o/s & n/s tail-lamp <i>Crushed</i>	1654.00	1400	
11	4 pcs	Rear o/s & n/s tail-lamp clips <i>NE</i>		20.00	✓
12	2 pcs	Rear o/s & n/s tail-lamp seal <i>NE</i>	60.00	40	
13	2 pcs	Rear o/s & n/s tail-lamp panel <i>Repair</i>	885.00	✓	
14	2 pcs	Rear regn. No. plate lamp <i>NE</i>	120.00	✓	
15	1 pc	Boot opener switch assy <i>NE</i>	580.00	✓	
16	1 pc	Rear boot cover <i>Dented</i>	2405.00	2127	
17	1 pc	Rear boot cover weatherstrip <i>NE</i>	253.50	✓	
18	1 pc	Rear boot cover emblem <i>NE</i>	63.70	✓	
19	2 pcs	Rear boot cover emblem clips <i>NE</i>		10.00	✓
20	4 pcs	Rear boot cover o/s & n/s stopper <i>3 AT</i>	31.20	✓	
21	2 pcs	Rear boot cover o/s & n/s hinges <i>NE</i>	87.80	✓	
22	2 pcs	Rear boot cover o/s & n/s hinge garnish <i>NE</i>	66.40	✓	
23	1 pc	Rear boot cover lock (Upper) <i>Dented</i>	416.00	✓	
24	1 pc	Rear boot cover moulding (de chrome) <i>NE</i>	345.60	✓	
25	1 pc	Rear spare wheel board cover (fiber) <i>NE</i>	351.50	✓	
26	1 pc	Rear exhaust muffler <i>Repair</i>	4735.50	✓	
27	4 pcs	Rear exhaust muffler mounting <i>NE</i>	160.00	✓	
28	1 pc	Rear o/s exhaust muffler heat shield <i>Dented</i>	430.40	180	
29	2 pcs	Rear o/s & n/s seat belt <i>NE</i>	2267.50	✓	
30	1 pc	Rear regn. no. plate <i>3MP</i>		120.00	✓
31	1 pc	Rear regn. no. plate bracket <i>3MP</i>		29.00	✓
Sub-Total:			18,843.50	2609.00	0.00
			10%	0%	10%
After Less %:			16,959.15	2609.00	0.00

770530

S.N. 1660

693477

	Labour	
1	To dismantle damaged parts, straighten & welding.	2,400.00 900
2	To spray painting.	2,200.00 900
3	To re-align rear chassis frame.	200.00 x
4	To remove & replace rear exhaust.	100.00 x
5	To remove & refit rear windscreen, rear seats & roof lining.	280.00 +
6	To remove & replace rear reverse sensor camera.	60.00 50
7	To reset seat belt	200.00 x
8	To reset front head lamps	30.00 x
9	To remove and replace rear tail-gate (Mechanism).	100 80
10	To remove and refit mechanism & motor <i>3M</i>	150 x
11	To reset rear tail gate motor	150 +
12	To remove & replace radiator. <i>3M</i>	150.00 +
13	To top up air con gas	x
14	To re-set electrical system.	250.00 x
15	To check wiring. <i>2020</i>	30.00
16	To re-seal anti-rust.	90.00 60
	Sub-Total:	5,990.00
	Total:	25,558.15
	After Less 20%:	20,446.52

Adrian C
 1/5 23/11/22
 06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 10614.77
 C/S: S.H.K. ✓