

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

OEY NICODEMUS EDRICK
BLK 216C COMPASSVALE DRIVE #03-566
SINGAPORE 543216

Contact : 87985734

TAX INVOICE

Repair Code : CLM15735

Date in : 22/11/2022

Vehicle Num. : SMK1813C

Model : TOYOTA SIENTA ELEGANCE (AUTO)

Chassis/Eng# : MHFZ28H3100063224/2NRX443701

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehd</i>	1	342.00	✓ 342.00
REAR BUMPER CENTER PROTECTOR (BLACK) <i>Dehd</i>	1	205.40	✓ 205.40
REAR BUMPER END SEAL COVER L/R <i>tom</i>	2	70.60	✓ 141.20
REAR BUMPER LOWER CENTER LAMP <i>auhd</i>	1	235.50	✓ 235.50
REAR BUMPER LOWER CENTER LAMP GARNISH <i>auhd</i>	1	60.60	✓ 60.60
REAR BUMPER REFLECTOR L/R <i>auhd</i>	2	65.00	✓ 130.00
REAR BUMPER REVERSE SENSOR <i>Rehd</i>	2	198.00	✓ 396.00
REAR BUMPER SIDE PROTECTOR (BLACK) L/R <i>auhd</i>	2	139.10	✓ 278.20
REAR BUMPER SIDE RETAINER L/R <i>auhd</i>	2	76.20	✓ 152.40
REAR BUMPER TOW HOOK COVER <i>at</i>	1	52.10	✓ 52.10
REAR END PANEL (INNER) <i>Dehd</i>	1	755.10	<i>580</i> 755.10
REAR END PANEL (OUTER) <i>Dehd</i>	1	469.60	✓ 469.60
REAR END PANEL ANTENNA SENSOR <i>Rehd</i>	1	78.00	✓ 78.00
REAR END PANEL INNER TOP GARNISH <i>Dehd</i>	1	167.30	✓ 167.30
REAR FENDER INNER TRIM BOARD L/R <i>Dehd</i>	2	680.30	✓ 1,360.60
REAR FENDER OUTER GARNISH L/R <i>auhd</i>	2	501.20	✓ 1,002.40
REAR FLOOR PANEL <i>Rehd</i>	1	755.10	<i>+</i> 755.10
REAR FLOOR PANEL TOP BOARD COVER <i>Dehd</i>	1	168.40	✓ 168.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

OEY NICODEMUS EDRICK
BLK 216C COMPASSVALE DRIVE #03-566
SINGAPORE 543216

Contact : 87985734

TAX INVOICE

Repair Code : CLM15735

Date in : 22/11/2022

Vehicle Num. : SMK1813C

Model : TOYOTA SIENTA ELEGANCE (AUTO)

Chassis/Eng# : MHFZ28H3100063224/2NRX443701

REAR FLOOR PANEL TRAY GARNISH	Deled	1	349.50	✓	349.50
REAR SPARE TYRE LOCK SCREW	Deled	1	69.90	1121.80	69.90
REAR TAILGATE	Distorted	1	1221.80	✓	1,221.80
REAR TAILGATE 'LOGO' EMBLEM	} see	1	57.70	✓	57.70
REAR TAILGATE 'SIENTA' EMBLEM		1	57.70	✓	57.70
REAR TAILGATE 'V' EMBLEM		1	30.10	✓	30.10
REAR TAILGATE CAMERA	Deled	1	986.70	600	986.70
REAR TAILGATE DAMPER L/R	Not in	2	331.50	+	663.00
REAR TAILGATE HINGES L/R	Not in	2	66.20	+	132.40
REAR TAILGATE INNER PULL HANDLE	Not in Deled	1	28.30	✓	28.30
REAR TAILGATE INNER RUBBER STOPPER L/R	Not in	2	12.70	+	25.40
REAR TAILGATE INNER TRIM BOARD	Cancelled	1	205.40	+	205.40
REAR TAILGATE LOCK STRIKER	Not in	1	27.90	+	27.90
REAR TAILGATE MECHANISM LOCK	Deled	1	506.20	385	506.20
REAR TAILGATE NUMBER PLATE LAMP L/R	Not in	2	395.90	+	791.80
REAR TAILGATE OUTER CHROME HANDLE	Cancelled	1	248.40	✓	248.40
REAR TAILGATE OUTER LOCK OPENER SWITCH	Not in	1	194.30	+	194.30
REAR TAILGATE REFLECTOR L/R	Cancelled	2	283.10	✓	566.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

OEY NICODEMUS EDRICK
BLK 216C COMPASSVALE DRIVE #03-566
SINGAPORE 543216

Contact : 87985734

TAX INVOICE

Repair Code : CLM15735

Date in : 22/11/2022

Vehicle Num. : SMK1813C

Model : TOYOTA SIENTA ELEGANCE (AUTO)

Chassis/Eng# : MHFZ28H3100063224/2NRX443701

REAR TAILGATE WEATHER STRIP	1	402.50	352.50	402.50
REAR TAILGATE WINDSCREEN MOULDING L/R	2	24.80	✓	49.60
REAR TAILGATE WINDSCREEN MOULDING UPPER	1	37.60	✓	37.60
REAR TAILGATE WINDSCREEN MOULDING L LOWER	1	37.60	✓	37.60
REAR TAILGATE WIPER ARM	1	160.50	T	160.50
REAR TAILGATE WIPER MOTOR	1	889.90	540.00	889.90
REAR TAILLAMP INNER PANEL L/R	2	100.50	100.50	201.00
REAR TAILLAMP L/R	2	439.00	✓	878.00
REAR TAILLAMP LOWER BRACKET L/R	2	76.20	11482.50	152.40
Subtotal before discount		8611.87	11482.50	15,721.70
Percentage discount 25%				3,930.43
Sub-total 1				11,791.28
REAR BUMPER CLIPS - SET	1	80.00	30	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	40.00	20	40.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	50.00	60	100.00
REAR FENDER OUTER GARNISH CLIPS L/R - SET	2	50.00	40	100.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	✓	50.00
REAR TAILGATE NUMBER PLATE	1	25.00	✓	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

OYE NICODEMUS EDRICK
BLK 216C COMPASSVALE DRIVE #03-566
SINGAPORE 543216

Contact : 87985734

TAX INVOICE

Repair Code : CLM15735

Date in : 22/11/2022

Vehicle Num. : SMK1813C

Model : TOYOTA SIENIA ELEGANCE (AUTO)

Chassis/Eng# : MHFZ28H3100063224/2NRX443701

REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	30	50.00
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET	1	40.00	20	40.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60	80.00
REAR TAILLAMP CLIPS L/R - SET	2	25.00	20	50.00
Subtotal before discount				615.00
Percentage discount 0%				0.00
Sub-total 2				615.00
Parts-total				12,406.28

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	3,530.00
Parts & Labour Total	15,936.28

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/S 24/11/22

07 Days

total: 11286.87.

L/S: 9K ✓