

國際汽車維修
KT MOTORWERK
Blk 3012 Bedok Ind Park E #01-2020 Singapore 480978.
(Bedok North Ave 4) Tel: 68387487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg No: 513734620

VEHICLE DETAILS

VEHICLE NO : JLJ 9896

MODEL : TOYOTA AVANZA

CHASSIS : PN2F602M002023730

TP Allianz.
Xiao Tony.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented.</i>	1	\$ 1,308.50	\$ 1,308.50
2	TAILGATE WEATHERSTRIP <i>nt.</i>	1	\$ 325.70	\$ 325.70
3	TAILGATE LOGO	1	\$ 98.60	\$ 98.60
4	TAILGATE EMBLEM 'AVANZA'	1	\$ 96.80	\$ 96.80
5	TAILGATE EMBLEM 'VVTI'	1	\$ 85.60	\$ 85.60
6	TAILGATE EMBLEM 'G'	1	\$ 82.60	\$ 82.60
7	TAILGATE EMBLEM '1.5'	1	\$ 85.60	\$ 85.60
8	TAILGATE INNER LOCK <i>Dented.</i>	1	\$ 361.61	\$ 361.61
9	TAILGATE INNER TRIM <i> Torn</i>	1	\$ 345.80	\$ 345.80
10	TAILGATE OUTER CHROME MOLDING <i>the new</i>	1	\$ 298.50	\$ 298.50
11	TAILGATE SIDE STOPPER <i>the new</i>	2	\$ 48.60	\$ 97.20
12	TAILGATE WINDSCREEN MOULDING <i>the new</i>	1	\$ 188.76	\$ 188.76
13	TAIL LAMP <i>LH cracked.</i>	2	\$ 345.20	\$ 690.40
14	TAIL LAMP INNER SEALER <i>the new</i>	2	\$ 38.00	\$ 76.00
15	REAR BUMPER <i>Dented.</i>	1	\$ 1,135.90	\$ 1,135.90
16	REAR BUMPER TOWING COVER <i>Missing</i>	1	\$ 45.20	\$ 45.20
17	REAR BUMPER SIDE RETAINER <i>the new</i>	2	\$ 85.20	\$ 170.40
18	REAR END PANEL (INNER) <i>the new</i>	1	\$ 689.50	\$ 689.50
19	REAR END PANEL (OUTER) <i>Dented.</i>	1	\$ 658.00	\$ 658.00
20	REAR END PANEL TOP GARNISH <i>Dented.</i>	1	\$ 276.90	\$ 276.90
21	REAR END PANEL LOCK GARNISH <i>the new</i>	2	\$ 198.00	\$ 396.00
22	REAR FENDER INNER TRIM	2	\$ 755.80	\$ 1,511.60
23	REAR FLOOR PANEL	1	\$ 659.80	\$ 659.80
24	REAR SPARE TYRE BRACKET	1	\$ 505.00	\$ 505.00
25	REAR EXHAUST PIPE	1	\$ 985.30	\$ 985.30
26	REAR EXHAUST MOUNTING	1	\$ 22.00	\$ 22.00

TOTAL PRICE \$ 11,197.27
LESS 25% \$ 2,799.32
SUB TOTAL PRICE \$ 8,397.95

3793.37

2845.02

S.N: 350

1180.
245.
60.
65.
58.
40.
45.
✓
220.
x.
x.
289.
+ 780
25.
x.
x.
x 350 (SN).
186.
x.
+
+
+
+
x.

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00 <i>x</i>
2	REAR BUMPER CLIPS <i>new</i>	10	\$ 5.50	\$ 55.00 <i>30</i>
3	TAILGATE INNER TRIM CLIPS <i>new</i>	10	\$ 5.50	\$ 55.00 <i>30</i>
4	TAILLAMP CLIPS <i>new</i>	4	\$ 5.50	\$ 22.00 <i>10</i>
5	REVERSE SENSOR <i>new</i>	1 SET	\$ 250.00	\$ 250.00 <i>2w</i>
6	REAR BUMPER TOP PROTECTOR <i>new</i>	1 SET	\$ 350.00	\$ 350.00 <i>+250</i>
7	REAR FENDER INNER TRIM CLIPS <i>new</i>	16	\$ 5.50	\$ 88.00 <i>+</i>
8	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	3	\$ 5.50	\$ 16.50 <i>✓</i>
9	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00 <i>x</i>
10	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00 <i>60</i>
11	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 <i>60</i>
TOTAL			\$ 1,136.50	

656.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	
1	TO PANEL BEAT, WELD, CUT, KNOCK, GRAZE, ADJUST	\$ 1,800.00	<i>8w</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,800.00	<i>8w</i>
3	TO SPRAY TOUGH COAT, RUST PROOFING	\$ 200.00	<i>60</i>
4	WIRING BULB CHECKING	\$ 80.00	<i>30</i>
5	REMOVE & REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 180.00	<i>50</i>
6	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>x</i>
7	TRANSFER TAILGATE MECHANISM	\$ 100.00	<i>60</i>
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>x</i>
9	REMOVE & REFIX REAR EXHAUST PIPE	\$ 150.00	<i>x</i>
10	REMOVE & REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>

15w

TOTAL \$ 4,780.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,534.45
TOTAL LABOUR COST : \$ 4,780.00
TOTAL REPAIR COST : \$ 14,314.45

total: 5771.52

2/5, 4.6k

06 Days

4.6k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature