

ASS. REC. BY:

REF:

AGW 22011776/KV

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STW 6699E Yr Regn: 02 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or MPV

Make: Toy Wish c.c. 1987

Colour: W. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 81900 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDGJ20W705002049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 193/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 20/11/22 D.O.I. 25/11/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

cls Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1	Est not ready, no GIA yet
28/11/22	11:30 @ 1750L Caber (Red 504975 749)

Date/Time, File Pass to?

: Prel. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation: _____
S + RS: _____

Fees

Others

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Not Authorized
1/1 Surp @ 1750/hr
Resurvey After Paint
3 days

Make/Model: TOYOTA WISH
 Engine/Chassis No.: JTDGJ20W705002049
 Date of accident: 20.11.22
 Damaged area: O/S

Date: 25/11/2022
 Claim Type: TP
 VRN: SJW6699E



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rocker panel o/s	<i>RC</i> 1	\$ 823.00	\$ 823.00
2	Rear fender o/s	<i>RC</i> 1	\$ 1,157.00	\$ 1,157.00
3	Rear fender cowling o/s	<i>RC</i> 1	\$ 185.00	\$ 185.00
4	Rear wheel hub n/s	<i>BS</i> 1	\$ 265.00	\$ 265.00
5	Rear shock absorber o/s	<i>RC</i> 1	\$ 355.00	\$ 355.00
6	Rear shock absorber top mount o/s	<i>RC</i> 1	\$ 53.00	\$ 53.00
7	Rear bumper retainer	<i>CMT 2/1</i>	\$ 65.00	\$ 130.00
8	Rear bumper <i>343</i>	<i>MJL 1/1</i>	\$ 845.00	\$ 845.00
Subtotal				\$ 3,813.00
List discount				25.00%
Total				\$ 2,859.75

X
X
X
X
X
X
X
X

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear alloy wheel o/s	<i>RC</i> 1	\$ 550.00	\$ 550.00
2	Rear tyre o/s	<i>RC</i> 1	\$ 280.00	\$ 280.00
3	Rocker panel sealant o/s	<i>RC</i> 1	\$ 100.00	\$ 100.00
4	Rear bumper clips	<i>RC</i> 12	\$ 5.50	\$ 66.00
5	Rear fender cowling clips o/s	<i>RC</i> 8	\$ 5.50	\$ 44.00
6	Sundries	<i>RC</i> 1	\$ 50.00	\$ 50.00
Total				\$ 1,090.00

380.00
X
X
X
X
X

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect wire harness and electrical component to facilitate repairs, reconnect and check functions.	0.5	\$ <i>RC</i> 100.00
3	To undercoat all affected portions after repair.	1	\$ <i>RC</i> 200.00

350.00
X
X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Repair Estimate

4	To remove and refit o/s rear tyre & rim for replacement. To perform tyre balancing.	0.25	\$	50.00
5	To remove and refit o/s rear undercarriage for replacement of parts.	1	\$	200.00
6	To conduct computerized 4 wheel alignment.	0.5	\$	100.00
7	Supply spray paint material and necessary items to respray affected area / panel.	5	\$	1,000.00
Total labour			\$	2,850.00

201
601
601
600

Estimate Grand Total			\$	6,799.75
-----------------------------	--	--	-----------	-----------------

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To reserve before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplemental items must be reserved and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: