

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH9489Y/23/11/2022 13:44**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER <i>cra</i>	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER CLIPS <i>nll</i>	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER SIDE BRACKET RH <i>cra</i>	20.00	0.00	*55.80 FL
4	1		*REAR FENDER RH <i>scr R</i>	20.00	0.00	*1,768.30 FL
5	1		*REAR BUMPER RUBBER MAT <i>nll</i>	0.00	0.00	*50.00 F

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)

2,355.50

- List Item Discount on L Items (\$\$)

461.10

Total Parts (\$\$)

1,894.40

ComfortDelGro Engineering Pte Ltd/SH9489Y/23/11/2022 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Parts: 537.20

Nett + 50

= 587.20

Total = 1817

~ 1800

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700750.00
2	SPRAY PAINTING CHARGE	New	500600.00
3	REMOVE/ REFIX REVERSE SENSOR	New	60.0030
Gross Labour Cost (S\$)			1,410.00

ComfortDelGro Engineering Pte Ltd/SH9489Y/23/11/2022 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1. for 90097659

24/11/22 3pm

P/P ~~1/2~~ After paint

3dunge

g

T=1800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date/Time: 23.11.2022 13:28

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5275059

JC NO305537427

STOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755
(R) (O)
(P)

COUNT CARD NO.

REGN NO: SH 9489Y

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL IONIQ(G3)

DATE/TIME IN 23.11.2022 11:35

YR OF MANU. 31.03.2022

TARGET DATE


CHASSIS CODE KMHC851CVLU194656

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 19.11.2022
NATURE: 3P 19.11.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 9489Y YY

Vehicle No.: SH 9489Y

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard