

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 10 Feb 2023

**Preliminary Advice**

Vehicle No	: SNB441J	Accident Date	: 22/11/2022
Make	: TOYOTA WISH	Policy No.	: SP2001934456-01
Assignment Date	: 23/11/2022	Excess	: S\$3,100.00
Date of Inspection	: 24/11/2022	Est. Duration of Repair	: 7
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES) BLK 9006 #01-200 TAMPINES ST 93 SINGAPORE		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,297.20 (inclusive supp: \$82.50)
Revised Amount	:S\$	8,633.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,633.20
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	35,405.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,595.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Kindly approve on supplementary.