

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011789/TQP3Q2**Date:** 01/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00106942200

**Claimant Vehicle No :** SMD7516H **Insured Vehicle No :** SKM1714T

Date of Loss: 19/11/2022 Nature of Claim: TP Claim No: SNM22D208424/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMD7516H**

Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A) Engine No: CZD142772

Reg. Date: 31/08/2018 (Man. Year: 2018) Chassis No: WVGZZZ1TZJW111479

Colour: Grey Odometer: 51742 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,956.53	2,248.02	1,708.51	43.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	5,680.00	1,640.00	22.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,276.53</b>	<b>7,928.02</b>	<b>3,348.51</b>	<b>29.69</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>789.36</b>	<b>554.96</b>	<b>234.40</b>	<b>29.69</b>
<b>Nett Amount (S\$)</b>	<b>12,065.89</b>	<b>8,482.98</b>	<b>3,582.91</b>	<b>29.69</b>

**INSPECTION**

Date of Assignment: 23/11/2022

Date Inspected: 24/11/2022 Inspected At: Volkswagen Centre Singapore (HQ)  
247 Alexandra Road  
Singapore 159934

Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Feb 2023)	
Parts:	N/A	VOLKSWAGEN TOURAN 1.4 TSI (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD7516H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*VW SIGN BLACK /BRIGHT CHRO	Necessary	121.15 FS	*121.15 FS
2	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -TOURAN	Necessary	83.16 FS	*83.16 FS
3	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,307.91 FS	*1,307.91 FS
4	1		*LOAD EDGE PROTECTION	Bent	260.55 FS	*260.55 FS
5	1		*SPOILER SATIN BLACK	Not Necessary	381.66 FS	*- FS
6	1		*BUMPER REINFORCEMENT	Not Necessary	706.15 FS	*- FS
7	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	75.42 FS	*- FS
8	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	51.62 FS	*- FS
9	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	51.62 FS	*- FS
10	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	42.04 FS	*- FS
11	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Deformed	42.04 FS	*42.04 FS
12	1		*REFLECTOR RHS REFLECTOR (OUTER)	Cut	77.69 FS	*77.69 FS
13	1		*REFLECTOR RHS REFLECTOR (INNER)	Cut	77.69 FS	*77.69 FS
14	1		*WHEELHOUSE PROTECTOR RHR FENDER LINER	Torn	235.33 FS	*235.33 FS
15	4		*RIVET	Necessary	5.28 FS	*5.28 FS
16	1		*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
17	1		*RHR FENDER FOIL	Necessary	37.22 FS	*37.22 FS
Total Parts (S\$)					3,956.53	2,248.02

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	3,360.00	2,520.00
4	SPRAY PAINT	New	3,200.00	2,400.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,320.00</b>	<b>5,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >