

3. REC BY: Taufik

REF:

CS/CT122011789/79p3.

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop this _____
of _____
Insured: _____
Policy No. _____
Claims Nil _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$115K
IDAC Accident Report Consistent? : Yes or No
GIA / PR Seen Consistent? : Yes or No
Est. Repairs: 7 days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SMD75164 Yr Regn: 2018 / Aug
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Volkswagen Touran 1.4 C.D 1395
Colour: Grey A/C: Insured / Std / Nil / NA
Sp. Reading: 51742 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: WVG 777 (T7JW 111479)
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / SR / STD A/Rim or
Tyre Size: F: 205/55R17
R: 205/55R17
BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO, or
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 24/1/22
Survey held at VW Alexandria
Des. of Damages: Fri / Rear / O/S / N/S / U/C / Roof top or
Rear o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised final fig \$7928.02, 7 days. (Red \$3348.51, 30%)

Date/Time, File Pass to?

☐ : Prel. Report

1) 27/01 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. \$.

Photos

Other

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Weekend (\$

Report Form No: MER-TP

Loss Sum / L.B. k: 7928.02

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
GOH
BOON YONG
37 LORONG M TELOK KURAU
#02-02
Singapore 425316

Document no.
Document date 22-11-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022034133/ 1
Job order date 22-11-2022
Service Advisor Dass Anthonidas Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMD7516H	5T13NZ	31-08-2018	WVGZZZ1TZW111479	Touran 1.4 CL GT110 TSID7F	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5TA853630A DPJ	Vw Sign Black/Bright Chro	1	pcs.	121.15	#1	121.15	129.63
5TA853687 ZZZ	Inscription Bright Chrome	1	pcs.	83.16	#1	83.16	88.98
	NAME PLATE - TOURAN						
5TA807417 GRU	Cover For Bumper Primed REAR BUMPER	1	pcs.	1,307.91	#1	1,307.91	1,399.46
5QA061195	Load Edge Protection	1	pcs.	260.55	#1	260.55	278.79
5TA807568A 9B9	Spoiler Satin Black	1	pcs.	381.66	#1	381.66	408.38
5TA807305	Bumper REINFORCEMENT	1	pcs.	706.15	#1	706.15	755.58
5TA807863	Attachment Strip BUMPER CTR BRACKET	1	pcs.	75.42	#1	75.42	80.70
5TA807453	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	51.62	#1	51.62	55.23
5TA807454	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	51.62	#1	51.62	55.23
5TA807393	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	42.04	#1	42.04	44.98
5TA807394	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	42.04	#1	42.04	44.98
5TA945104	Reflector RHS REFLECTOR (OUTER)	1	pcs.	77.69	#1	77.69	83.13
5TA945106	Reflector RHS REFLECTOR (INNER)	1	pcs.	77.69	#1	77.69	83.13
5TA810972A	Wheelhouse Protector RHR FENDER LINER	1	pcs.	235.33	#1	235.33	251.80
WHT005263	Rivet	4	pcs.	1.32	#1	5.28	5.65
	LABOUR	3	pcs.	840.00	#1	3,360.00	3,595.20
	SPRAY PAINT	3	pcs.	800.00	#1	3,200.00	3,424.00
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	CHINA TAIPING DIRECT DOA:19/11/2022						
	TP VEH NO:SKM1714T						
	SURVEY BY:						

Quotation valid till 29-11-2022

7928.02, 7 days

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	10,479.31	7%	786.75	11,239.31	12,026.06
Total	760.00	10,479.31		786.75	11,239.31	12,026.06

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
GOH
BOON YONG
37 LORONG M TELOK KURAU
#02-02
Singapore 425316

Document no.
Document date 22-11-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022034133/ 1
Job order date 22-11-2022
Service Advisor Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMD7516H	5T13NZ	31-08-2018	WVGZZZ1TZW111479	Touran 1.4 CL GT110 TSID7F	20

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

Taufik 97495749/62563561
'WP' 24/11/22 @ 2:15pm
Resurvey before paint
taufik@lkkauto.com
6-7 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary or Omitted List



VEHICLE NUMBER: SMD7516H

MODEL Touran 1.4

CLAIMS DETAILS

LABOUR DESCRIPTION		AMOUNT		
Total				\$0.00

No.	Item No.	Description	Qty	Unit Price	Discount	Amount
1	5TA821714D	RHR FENDER FOIL	1	\$ 37.22	nil ✓	\$ 37.22
			TOTAL:			\$37.22

Total Labour & Parts

\$37.22

SURVEY By



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK SERI ALAM
Daerah : SERI ALAM
Kontinjen : JOHOR
No Repot : TRAFIK KULAIJAYA/012528/22
Tarikh : 21/11/2022
Waktu : 1335 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R170235
No Repot Bersangkut : TRAFIK
KULAIJAYA/012466/22

Butir-butir Penerima Repot

Nama : MOHD FAZLY BIN MOHD SHARIF

No Personel : R166278

Pangkat : KPL

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : GOH BOON YONG

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : K3408166Z

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 15/08/1978

Umur : 44 tahun 3 bulan

Keturunan : Cina

Warganegara : SINGAPORE

Pekerjaan : PENGURUS

Alamat Tempat Tinggal : BLK 37LORONG M TELOK KURAU #02-02, 0202 SINGAPORE

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 96396301

Pengadu Menyatakan:-

PADA 19/11/2022 JAM LEBIH KURANG 17:15 PETANG, SAYA MEMANDU MOTOKAR NOMBOR SMD7516H JENIS VOLSWAGEN DARI MELAKA MENUJU KE DESARU. PADA KETIKA ITU, APABILA SAYA SAMPAI DI KM47.3 LEBUH RAYA UTARA SELATAN, KEADAAN JALAN SESAK DAN SAYA BERHENTI KERANA KENDERAAN DI HADAPAN SAYA BERHENTI. PADA MASA YANG SAMA, SAYA DENGAR BUNYI YANG KUAT DARI ARAH BELAKANG. SAYA TURUN DAN DAPATI SEBUAH MPV NOMBOR SKM1714T TELAH MELANGGAR KENDERAAN SAYA. DALAM KEJADIAN ITU, SAYA TIDAK MENGALAMI APA-APA KECEDERAAN. KEROSAKAN MOTOKAR SAYA IALAH BUMPER BELAKANG, BONET BELAKANG, SENSOR BELAKANG DAN LAIN-LAIN ROSAK TAK PASTI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

: A9026987 | 21/11/2022 03:39:03 PM