

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Car In

GST REG. NO : M2 - 0020081 - X

ESTIMATE

22 NOV 2022

Estimate No. : b1 64098
Date Estimated : 22/11/2022
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Khong Heng Kow Arthur
53 Mariam Walk

Singapore 507134

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA53M	WBA7K120107H57654	28/04/2021	116i Hatch	14218

DESCRIPTION

To replace front bumper, fender front rh, front rh door, rear bumper and make good of rear rh fender.

3825 3400 5,100.00

To painting front bumper, front rh fender, rear right fender, front rh door and rear bumper.

5001 4950 5,190.00

To tow accident vehicle to PML workshop.

✓ 150.00

To replace left or right headlight.

457 481.00

To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.

280 295.00

To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (1 door).

504 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for (X2) proper function.

336 168 177.00

To carry out body cavity preservation. (Per panel).

224 236.00

Sundries.

10927. ✓ 150.00

Total Labour 1: 12,310.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING RIVET	12	0.95	11.40
FRT RH SIDE PANEL	1	639.70	639.70
FRT RH DOOR	1	1,159.75	1,159.75
FRT BUMPER PANEL PRIMED (LINES PDC/	1	950.80	950.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 64098
Date Estimated : 22/11/2022
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA53M	WBA7K120107H57654	28/04/2021	116i Hatch	14218

DESCRIPTION	QTY	PRIC	VALUE
RH FOG LAMP SUPPORT	1	73.85	un 73.85
REAR BUMPER RH SIDE GUIDE	1	136.30	un 136.30
REAR BUMPER TRIM PANEL (LUX PDC/PMA GROMMET	1	1,088.30	de 1,088.30
RH OUTSIDE MIRROR HEATED WITH MEMOR	2	0.80	un 1.60
RH OUTSIDE MIRROR COVER CAP PRIMED	1	584.40	un 584.40
FRT RH WHEEL ARCH COVER	1	130.05	un 130.05
PLAQUE 82MM	1	138.40	de 138.40
(S/L) DOOR WEATHERSTRIP	1	72.85	un 72.85
RH HEADLIGHT BI LED	1	139.10	un 139.10
	1	2,399.10	cut 2,399.10

Total Parts : 7,525.60
7304.05

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 23/11/22 @ 12pm Excess \$ \$ _____

Surveyor's Name Taufik Sign _____

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date WP Time 12pm

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail taufik@phantom.com

No. of Working Days Recommend 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	12,310.00
Parts	:	7,525.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,388.49
Grand Total	:	21,224.09

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **