



AKA AUTO PTE LTD
25 KAKI BUKIT ROAD 4,
#05-36, #05-37
SYNERGY @ KB
S417800
H 81880754

ROC 201700008R

TP AYA
Veron

ESTIMATED REPAIR CHECKLIST

23 Nov 2022

TO :	VEHICLE REGISTRATION NO.: SKP7809Z
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: LEXUS / IS250C
CLAIM TYPE : OD PARTY CLAIM	CHASSIS NUMBER: KMHD841CMJU739896
ACCIDENT DATE/TIME :	CONTACT PERSON :

PARTS	QTY	PER UNIT	PRICES
1 REAR BUMPER <i>Deband</i>	1	\$ 986.40	\$ 986.40 ✓
2 REAR BUMPER SIDE HOLDER RH <i>hangd</i>	1	\$ 130.20	\$ 130.20 68. ✓
3 REAR RH FENDER <i>Revis</i>	1	\$ 2,051.90	\$ 2,051.90 x
4 REAR RH FENDER GLASS MOULDING <i>stem</i>	1	\$ 85.40	\$ 85.40 x
		Sub total	SUBTOTAL : \$ 3,253.90
		Less 10%	LESS 10% : \$ 325.39
		Total List	PARTS TOTAL : \$ 2,928.51

1054.40
less 10%: 948.56

SPECIAL NETT	QTY	PER UNIT	PRICES
1 REAR BUMPER CLIPS <i>mu</i>	1 SET	\$ 50.00	\$ 50.00 ✓
2 REAR RH FENDER GLASS SEALANT <i>stem</i>	1 SET	\$ 40.00	\$ 40.00 x
3 PAINT PROTECTION <i>stem</i>	1 SET	\$ 500.00	\$ 500.00 400. ✓
		Sub total	S/N TOTAL : \$ 590.00

450

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 800.00	300
2 SPRAY PAINTING	\$ 800.00	400. ✓
3 WIRING	\$ 50.00	✓
4 TO REMOVE REVERSE SENSOR	\$ 100.00	50
5 TO SPRAY TUFF COAT	\$ 100.00	40. ✓
6 TO REMOVE REAR FENDER GLASS	\$ 100.00	x. ✓
LABOR TOTAL :	\$ 1,950.00	

840

5468.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
1/s 23/11/22

03 Days.

total: 2238.96

1/s 1-8K

1-8K