



Final Report

Estimate No. : **b1 64115**
Date Estimated : **23/11/2022**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

- ESTIMATE REPAIR FOR -

Ma Yongtao
99 Robertson Quay
#40-11

Singapore 238258

- ACCOUNT - 224093

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SMN720C	WBACR620509F35257	05/04/2021	X5 xDrive40i	29678

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front LH door and attachments include making good the rear LH door and knocking out dents caused by the accident	1,275.00	0.00	1,275.00	
To spray paint front LH door and handle and rear LH door	2,042.00	0.00	2,042.00	
To check electrical wiring system at the LH section for proper function	168.00	0.00	168.00	
To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function (x1)	504.00	0.00	504.00	
To carry out body cavity preservation (Per panel)	112.00	0.00	112.00	
Sundries	80.00	0.00	80.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH DOOR	2,319.45	1.00	0.00	2,319.45
LH DOOR OUTER HANDLE PRIMED (CA/OVT	98.35	1.00	0.00	98.35
(S/L) DOOR WEATHERSTRIP	208.60	1.00	0.00	208.60
(S/L) LH A PILLAR CAULKING	51.10	1.00	0.00	51.10

SUPPLEMENTARY ITEMS

Total Labour :	4,181.00
Total Parts :	2,677.50
Total Labour & Parts before GST :	6,858.50

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

