



Supplementary

Estimate No. : **b1 64115**
Date Estimated : **23/11/2022**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

- ESTIMATE REPAIR FOR -

Ma Yongtao
99 Robertson Quay
#40-11

Singapore 238258

- ACCOUNT - 224093

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SMN720C	WBACR620509F35257	05/04/2021	X5 xDrive40i	29678

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace front LH door and attachments include making good the rear LH door and knocking out dents caused by the accident	1,275.00	0.00	1,275.00

* To spray paint front LH door and handle and rear LH door	2,042.00	0.00	2,042.00
--	----------	------	----------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

SUPPLEMENTARY ITEMS

Total Labour :	3,317.00
Total Parts :	
Total Labour & Parts :	3,317.00
Deduction for Excess :	
Total Repair Costs less Excess:	3,317.00
GST @7%:	232.19
Grand Total :	3,549.19