

ASS. R. = 4.01 Taufan

REF: CE4/AIS 22011795/Tp93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp. Est Vehicle No: _____

at Work shop/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$330K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMN720C

Yr Regn: 2021 April

Type: Car / M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X5

c.c. 2998

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: —

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WISACR 620 509 F35257

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S / Rim / STD A / Rim or

Tyre Size: F: 275/40R21

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 24/11/22

Survey held at Performance Auto

Des. of Damages Fr / Rear / O/S / NI / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

☐

: _____

\$ + RS. \$ _____

Photos _____

Others _____

Report Format: _____

Lump Sum / L.B.A. (\$) _____

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Car In
(LKK)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

23 NOV 2022

Estimate No. : b1 64115 Page No. : 1 of 5
Date Estimated : 23/11/2022
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Ma Yongtao
99 Robertson Quay
#40-11

Singapore 238258

- ACCOUNT - 224093

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMN720C	WBACR620509F35257	05/04/2021	X5 xDrive40i	29678

DESCRIPTION

To replace front left door and make good rear left door.

1275 850 2,550.00

To painting front left door and rear left door.

2042 1972 2,076.00

To check electrical wiring system

168 177.00

To transfer lock mechanism from old to new door including
conduct check on new door power window system for proper
function. (1 door).

504 531.00

To carry out body cavity preservation.
(Per panel).

112 118.00

To supply and install front left or right window glass
solar film.

un x 425.00

Sundries.

4181 80 ? 150.00

Total Labour 1: 6,027.00

DESCRIPTION

FRT LH DOOR

QTY PRIC

VALUE

PRIME COATED COVERING

1 2,319.45

67 2,319.45

LH DOOR OUTER HANDLE PRIMED (CA/OVT

1 51.20

un x 51.20

LH DOOR HANDLE OUTSIDE CARRIER

1 98.35

do's 98.35

FRT LH DOOR SIDE WINDOW GLASS

1 183.90

un x 183.90

FRT LH DOOR CARRIER

1 367.80

un x 367.80

(S/L) DOOR WEATHERSTRIP

1 724.95

un x 724.95

(S/L) LH A PILLAR CAULKING

1 208.60

net 208.60

1 51.10

del 51.10

Total Parts : 4,005.35

2677.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 64115
Date Estimated : 23/11/2022
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMN720C	WBACR620509F35257	05/04/2021	X5 xDrive40i	29678

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfakh 97495749 / 62563561
WP 24/11/22 @ 420pm
Resurvey before paint
Tanfakh @ lkkauto.com
3-4 days

4181
2677.55
6858.50
24 days



Labour 1	:	6,027.00
Parts	:	4,005.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	702.26