


PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Hui Rong

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 8342 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURIZE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ✓ 780	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00 1000 (Without Lock Corner) ✓	
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES.	\$ 3,000.00 1100 (With lock Carrier) +500 ✓	
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 192	
TOTAL LABOUR CHARGES		\$ 10,394.00	

+ 4 days.


Carvin

28/11/22

wip 251472

PREMIUM AUTOMOBILES

Bent.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 8342 E

ATG-Adnan

-4/7 days.

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Del'd</i>	1	\$ 2,377.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 612.00	✓
3	FRONT BUMPER SECURING STRIP - LH / RH ?	2	\$ 79.00	✓
4	FRONT BUMPER GRILLE - CENTER <i>Carved</i>	1	\$ 219.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 254.00	✓
6	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1	\$ 72.00	✓
7	RADIATOR GRILLE <i>Carved</i>	1	\$ 1,277.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 151.00	✓
9	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 139.00	✓
10	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 899.00	✓
11	FRONT BUMPER TOP COVER <i>Del'd</i>	1	\$ 143.00	✓
12	CAUTION SIGN STICKER <i>new</i>	1	\$ 16.00	✓
13	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00	✓
14	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 41.00	✓
15	FRONT BUMPER BRACKET <i>Carved</i>	1	\$ 154.00	✓
16	FRONT BUMPER SUPPORT (LH) / RH <i>2A Dmg</i>	2	\$ 64.00	✓ 32.
17	HORN HIGH TONE - LH <i>new</i>	1	\$ 134.00	✓
18	HORN BRACKET - LH <i>new</i>	1	\$ 33.00	✓
19	FRONT FENDER - LH <i>new Buckled</i>	1	\$ 861.00	✓
20	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 225.00	✓


SUB TOTAL SPARE PARTS

: \$ 7,759.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5LL 8342 E


			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT - LH <i>incl</i>	1	\$ 8,294.00	✓
42	HEADLIGHT POWER MODULE	1	\$ 842.00	+
43	HEADLIGHT CONTROL UNIT <i>new</i>	1	\$ 840.00	+
44	HEADLIGHT HOSE - LH	1	\$ 42.00	+
45	HEADLIGHT COMPENSATING PIECE <i>new</i>	1	\$ 45.00	+
46	HEADLIGHT COMPENSATING PIECE <i>new</i>	1	\$ 47.00	+
47	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00	+
48	LIFT CYLINDER - LH <i>new</i>	1	\$ 231.00	+
49	LIFT CYLINDER BRACKET <i>new</i>	1	\$ 7.00	+
50	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	+
51	LOCK CARRIER <i>new</i>	1	\$ 1,478.00	✓
52	LOCK CARRIER SUPPORT - LH <i>new</i>	1	\$ 43.00	+
53	A/C CONDENSER <i>new</i>	1	\$ 683.00	+
54	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 186.00	+
55	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 381.00	+
56	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 277.00	+
57	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 21.00	+
58	ADDITIONAL RADIATOR - LOWER CENTRE <i>new</i>	1	\$ 545.00	+
59	RADIATOR <i>new</i>	1	\$ 699.00	+
60	READY-MIX COOLANT <i>new</i>	6	\$ 297.00	+

SUB TOTAL SPARE PARTS

: \$ 15,110.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 8342 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	RADIATOR AIR GUIDE LH RH INNER } LH Dmg	2	\$	64.00	32
62	RADIATOR AIR GUIDE LH / RH OUTER }	2	\$	28.00	14.
63	RADIATOR AIR GUIDE - UPPER } new	1	\$	19.00	+
64	RADIATOR AIR GUIDE - LOWER }	1	\$	25.00	+
65	RADIATOR AIR GUIDE FAN RING new	1	\$	292.00	+
66	RADIATOR FAN CONTROL UNIT new	1	\$	2,489.00	+
67	FRONT NO PLATE Perfected	S/N	\$	60.00	✓
68	SUNDRIES ?		\$	500.00	?
TOTAL SPARE PARTS		:	\$	31,813.00	
TOTAL LABOUR CHARGES		:	\$	10,394.00	
GRAND TOTAL		:	\$	42,207.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian
 Resurveyed.
 H.S.

Add 4 days for
 Replacement of fender
 and lock carrier.
 H.S.