

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Hui Rong

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 8342 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ✓ 250 ✓	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ✓ 780 ✓	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1500 4,900.00 ✓	1000 (Without Lock Carrier) +500 ✓
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES.	\$ 1600 3,000.00 ✓	2250 (With Lock Carrier) +500 ✓
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓ 792	✓
TOTAL LABOUR CHARGES		: \$ 10,394.00	

+ 4 days

Car-in

28/11/22

w/p 251472

PREMIUM AUTOMOBILES

Bersin



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 8342 E

ATG - Admin
- 4/7 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>del</i>	1	\$ 2,377.00	✓ 1901.60
2	FRONT BUMPER FIXING PARTS <i>neu</i>	1	\$ 612.00	✓ x
3	FRONT BUMPER SECURING STRIP - LH / RH <i>? x neu</i>	2	\$ 79.00	✓ x
4	FRONT BUMPER GRILLE - CENTER <i>Curled</i>	1	\$ 219.00	✓ 174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	1	\$ 254.00	✓ x
6	FRONT BUMPER AIR GUIDE - LH <i>neu</i>	1	\$ 72.00	✓ x
7	RADIATOR GRILLE <i>Curled</i>	1	\$ 1,277.00	✓ 1021.60
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>neu</i>	1	\$ 151.00	✓ x
9	FRONT BUMPER FOAM FILLER PIECE <i>? x neu</i>	1	\$ 139.00	✓ x
10	FRONT BUMPER REINFORCEMENT BEAM <i>? x neu</i>	1	\$ 899.00	✓ x
11	FRONT BUMPER TOP COVER <i>Del</i>	1	\$ 143.00	✓ 114
12	CAUTION SIGN STICKER <i>neu</i>	1	\$ 16.00	✓ 12.40
13	AIR CONDITIONER STICKER	1	\$ 9.00	✓ 6.64
14	FRONT BUMPER GUIDE SECTION - LH <i>neu</i>	1	\$ 41.00	✓ x
15	FRONT BUMPER BRACKET <i>Curled</i>	1	\$ 154.00	✓ 122.8
16	FRONT BUMPER SUPPORT (LH) / RH <i>2A Dmg</i>	2	\$ 64.00	✓ 32.25.6
17	HORN HIGH TONE - LH <i>neu</i>	1	\$ 134.00	✓
18	HORN BRACKET - LH <i>neu</i>	1	\$ 33.00	✓
19	FRONT FENDER - LH <i>neu Buckled</i>	1	\$ 861.00	✓ 688.80
20	FRONT FENDER ATTACHMENT PARTS <i>neu</i>	1	\$ 225.00	✓
SUB TOTAL SPARE PARTS			\$ 7,759.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 8342 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 81.00	+ X
22	FRONT FENDER BRACKET - LH	1	\$ 41.00	+ X
23	FRONT FENDER BRACE - LH	1	\$ 132.00	+ X
24	FRONT FENDER RIVET	6	\$ 23.00	+ 18.24
25	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	1	\$ 55.00	+
26	FRONT WHEEL HOUSING LINER - LH	1	\$ 260.00	+
27	FRONT WHEEL SPOILER	1	\$ 82.00	+
28	FRONT WHEEL SPOILER END PLATE - LH	1	\$ 39.00	+
29	FRONT WHEEL SPOILER STONE CHIP GUARD	1	\$ 57.00	+
30	FRONT FENDER LEDGE COVER - LONG	1	\$ 35.00	+
31	FRONT FENDER LEDGE COVER - SHORT	1	\$ 26.00	+
32	BONNET	1	\$ 3,425.00	✓ 2740
33	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	✓ 73.20
34	BONNET HINGE - LH / RH	2	\$ 680.00	+
35	BONNET STRIKER - LH	1	\$ 56.00	+
36	BONNET LOCK	1	\$ 228.00	+
37	BONNET BOWDEN CABLE	1	\$ 64.00	+
38	BONNET RELEASE LEVER	1	\$ 15.00	+
39	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	+
40	BONNET RELEASE CABLE COVER	1	\$ 11.00	+
SUB TOTAL SPARE PARTS		:	\$ 5,457.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

1949

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 8342 E

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT - LH <i>incl</i>	1	\$ 8,294.00	✓ 6635.20
42	HEADLIGHT POWER MODULE	1	\$ 842.00	+
43	HEADLIGHT CONTROL UNIT	1	\$ 840.00	+
44	HEADLIGHT HOSE - LH	1	\$ 42.00	+
45	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00	+
46	HEADLIGHT COMPENSATING PIECE	1	\$ 47.00	+
47	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00	+
48	LIFT CYLINDER - LH	1	\$ 231.00	+
49	LIFT CYLINDER BRACKET	1	\$ 7.00	+
50	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	+
51	LOCK CARRIER <i>incl. x new</i>	1	\$ 1,478.00	✓
52	LOCK CARRIER SUPPORT - LH <i>new</i>	1	\$ 43.00	+
53	A/C CONDENSER <i>new Dented</i>	1	\$ 683.00	✓ 546
54	A/C CONDENSER REFRIGERANT LINE	1	\$ 186.00	+
55	A/C CONDENSER REFRIGERANT LINE	1	\$ 381.00	+
56	A/C CONDENSER REFRIGERANT LINE	1	\$ 277.00	+
57	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	+
58	ADDITIONAL RADIATOR - LOWER CENTRE	1	\$ 545.00	+
59	RADIATOR	1	\$ 699.00	+
60	READY-MIX COOLANT	6	\$ 297.00	+

SUB TOTAL SPARE PARTS

\$ 15,110.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 8342 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	RADIATOR AIR GUIDE LH RH INNER } LH Dmd	2	\$ 64.00	✓	3 2 25.6
62	RADIATOR AIR GUIDE LH / RH OUTER	2	\$ 28.00	✓	14. 10.88
63	RADIATOR AIR GUIDE - UPPER } new	1	\$ 19.00	+	
64	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00	+	
65	RADIATOR AIR GUIDE FAN RING new	1	\$ 292.00	+	
66	RADIATOR FAN CONTROL UNIT new	1	\$ 2,489.00	+	
67	FRONT NO PLATE Dented	S/N	\$ 60.00	✓	
68	SUNDRIES Rec.		\$ 500.00	?	66.64
TOTAL SPARE PARTS		:	\$ 31,813.00		
TOTAL LABOUR CHARGES		:	\$ 10,394.00		
GRAND TOTAL		:	\$ 42,207.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

days of repairs 5 days

Adrian
 Resurveyed.
 H.S.

Add 4 days for
 Replacement of fender
 and lock carrier.
 H.S.