



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01030/2022/EQ
DATE : 19-Nov-22
WIP : 51269

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/11/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WEE TENG HENG
ADDRESS : 30 BUKIT BATOK STREET 21
#08-02
SINGAPORE 659636
TELEPHONE : HP +65 98251535
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210149198
VEHICLE NO : **SND 1621 P**
MODEL CODE : AUDI A1 SB S-LINE 1.0 TFS
MODEL YEAR : 10/12/2021
ENGINE NO : DKJ 116550
CHASSIS NO : WAUZZZGB5NR005087
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Nov-22
PLACE OF ACCIDENT : PIE (EAST TO WEST)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 1621 P - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	7
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1000
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND HINGES.	\$ 4,000.00	1650
TOTAL LABOUR CHARGES - FRONT		: \$ 12,060.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 1621 P - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	380.00	✓
2	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY .	S/N \$	1,400.00	✓
3	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID AND SPARE WHEEL HOUSING. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	2000 ✓
4	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$	3,500.00	2200 ✓
5	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$	480.00	X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES - FRONT & REAR		:	\$ 22,212.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 1621 P - FRONT

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT			REMARKS
1	FRONT BUMPER <i>Debon d</i>	1	\$	2,377.00	✓	
2	FRONT BUMPER FIXING PARTS <i>mean</i>	1	\$	143.00	+	
3	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>mean</i>	2	\$	632.00	+	
4	FRONT BUMPER SPOILER	1	\$	239.00	+	
5	FRONT BUMPER GRILLE - CENTER <i>mean</i>	1	\$	219.00	+	
6	FRONT BUMPER CLOSING ELEMENT	1	\$	235.00	x	
7	RADIATOR GRILLE <i>Chub d</i>	1	\$	1,026.00	✓	
8	RADIATOR GRILLE CLOSING ELEMENT	1	\$	178.00	?	
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$	769.00	?	
10	FRONT BUMPER FOAM FILLER PIECE	1	\$	131.00	?	
11	FRONT BUMPER GUIDE PROFILE - LH / RH <i>LH ?</i>	2	\$	80.00	?	
12	FRONT BUMPER TOP COVER <i>mean</i>	1	\$	137.00	+	
13	CAUTION SIGN STICKER	1	\$	16.00	+	
14	FRONT TYPE PLATE "AC" REFRIGERANT FILL VOLUME <i>mean</i>	1	\$	21.00	+	
15	HORN LOW TONE - RH <i>mean</i>	1	\$	146.00	+	
16	HORN HIGH TONE - LH	1	\$	154.00	+	
17	HORN BRACKET HIGH TONE - LH <i>mean</i>	1	\$	46.00	+	
18	HORN RETAINER LOW TONE - RH	1	\$	34.00	+	
19	FRONT FENDER - LH / RH <i>Ret Right, LH mean</i>	2	\$	2,102.00	x	
20	FRONT FENDER BRACE - LH / RH <i>mean</i>	2	\$	120.00	x	
SUB TOTAL SPARE PARTS - FRONT			\$	8,805.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 1621 P - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - LH / RH <i>3 pc</i>	2	\$ 82.00 +	
22	FRONT FENDER BRACKET - LH / RH	2	\$ 30.00 +	
23	"S-LINE" INSCRIPTION <i>Rec RH</i>	2	\$ 266.00 133.	
24	FRONT WHEEL HOUSING LINER - LH / RH <i>Rec m</i>	2	\$ 388.00 +	
25	BONNET <i>Dented</i>	1	\$ 2,802.00 ✓	
26	BONNET HINGE - LH / RH <i>Rec m</i>	2	\$ 136.00 +	
27	BONNET IMPACT PROTECTION - RH / LH / CENTER <i>Rec</i>	3	\$ 102.00 ✓	
28	BONNET ENGINE SOUND ABSORBER <i>Rec m</i>	1	\$ 244.00 +	
29	BONNET FLAP GASKET <i>3 pc m</i>	1	\$ 103.00 +	
30	BONNET FLAP SUPPORT	1	\$ 86.00 +	
31	BONNET BOWDEN CABLE - CENTER / LH / RH <i>Rec m</i>	3	\$ 156.00 +	
32	BONNET LOCK - LH / RH <i>2</i>	2	\$ 455.00 +	
33	BONNET STRIKER - LH / RH	2	\$ 222.00 +	
34	BONNET RELEASE LEVER <i>Rec m</i>	1	\$ 16.00 +	
35	BONNET RELEASE CABLE COVER	1	\$ 11.00 +	
36	BONNET LOCK CABLE	1	\$ 52.00 +	
37	FRONT BUMPER GUIDE SECTION - LH / RH <i>RH ?</i>	2	\$ 240.00 ?	
38	HEADLIGHT - LH / RH <i>RH cancelled</i>	2	\$ 9,124.00 4562	
39	LIFT CYLINDER - LH / RH <i>3 pc m</i>	2	\$ 312.00 +	
40	LIFT CYLINDER HOSE	1	\$ 68.00 +	
SUB TOTAL SPARE PARTS - FRONT			\$ 14,895.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 1621 P - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LOCK CARRIER ?	1	\$ 1,412.00	?
42	HEADLIGHT BRACE - LH / RH UPPER <i>new ?</i>	2	\$ 170.00	?
43	A/C CONDENSER ?	1	\$ 541.00	?
44	RADIATOR AIR GUIDE LH / RH ?	2	\$ 86.00	?
45	RADIATOR AIR GUIDE SEAL - RH ?	1	\$ 14.00	?
46	READY-MIX COOLANT ?	6	\$ 297.00	?
47	AIR INTAKE DUCT PIPE <i>new</i>	1	\$ 55.00	+
48	AIR INTAKE INLET CHANNEL DUCT HOSE <i>new</i>	1	\$ 44.00	+
49	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓
TOTAL SPARE PARTS - FRONT		:	\$ 26,379.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 1621 P - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Distorted</i>	1	\$ 2,317.00	✓	
2	REAR BUMPER ADAPTER - LH / RH ?	2	\$ 48.00	?	
3	REAR BUMPER DIFFUSER <i>Distorted</i>	1	\$ 469.00	✓	
4	REAR BUMPER GRILLE - LH / RH <i>Lt</i>	2	\$ 506.00	✓	
5	REAR BUMPER LOWER TRIM - CENTER <i>Distorted</i>	1	\$ 239.00	✓	
6	REAR BUMPER GRILLE - CENTER <i>Distorted</i>	1	\$ 96.00	✓	
7	REAR BUMPER REFLECTOR - LH / RH <i>new</i>	2	\$ 68.00	✗	
8	REAR INNER TAIL LIGHT - LH / RH <i>new</i>	2	\$ 1,796.00	✗	
9	REAR BUMPER REINFORCEMENT BEAM ?	1	\$ 564.00	?	
10	REAR BUMPER SECURING STRIP - CENTER <i>Distorted</i>	1	\$ 151.00	✓	
11	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 109.00	✗	
12	REAR BUMPER GUIDE PROFILE - LH / RH ?	2	\$ 126.00	?	
13	REAR PARKING AID SENSOR - INNER / OUTER ?	4	\$ 1,062.00	?	
14	REAR PARKING AID SEAL RING ?	4	\$ 10.00	?	
15	REAR BUMPER WIRING SET ?	1	\$ 201.00	?	
16	PACKING ADHESIVE <i>2m</i>	1	\$ 21.00	✓	
17	AUDI EMBLEM <i>2m</i>	1	\$ 144.00	✓	
18	"A1" INSCRIPTION	1	\$ 104.00	✓	
19	REAR CROSS PANEL <i>Dented</i>	1	\$ 333.00	✓	
20	REAR CROSS PANEL REINFORCEMENT <i>Dented</i>	1	\$ 673.00	✓	
SUB TOTAL SPARE PARTS - REAR		:	\$ 9,037.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 1621 P - REAR

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR CROSS PANEL CONNECTING PLATE - LH / RH ?	2	\$ 92.00 ?	
22	REAR UNDERBODY TRIM - LH / RH ?	2	\$ 144.00 ?	
23	REAR SILENCER <i>new</i>	1	\$ 498.00 +	
24	EXHAUST SYSTEM RETAINER <i>3 new</i>	1	\$ 58.00 +	
25	REAR SILENCER HEAT SHIELD	1	\$ 209.00 +	
26	REAR AERIAL KEY ACCESS - CENTRE ?	1	\$ 79.00 ?	
27	ACRYLIC SEALANT <i>3</i>	S/N	\$ 180.00 ✓	
28	CAVITY WAX <i>new</i>	S/N	\$ 140.00 ✓	
29	STONE CHIP	S/N	\$ 180.00 ✓	
30	METAL FILLER POWDER	S/N	\$ 280.00 ✓	
31	SUNDRIES ?		\$ 600.00 ?	
TOTAL SPARE PARTS - FRONT & REAR		:	\$ 37,876.00	
TOTAL LABOUR CHARGES - FRONT & REAR		:	\$ 22,212.00	
GRAND TOTAL		:	\$ 60,088.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian King

SURVEYED DATE

:

28/11/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorized, 12 Days - Front 5 Days - Rev 7 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT