

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584
Company Reg No: 201929175W

Vehicle number: SKC5851G
Make & Model: Mercedes Benz CLA180
Chassis number: WDD1173422N316563

Date of survey:
Name of surveyor:
Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Booltid	1	\$ 1,532.00
2	Bootlid centre emblem	1	\$ 78.00
3	Bootlid lock	1	\$ 316.00
4	Bootlid lock catch	1	\$ 56.00
5	Bootlid RH hinge	1	\$ 189.00
6	Bootlid LH hinge	1	\$ 189.00
7	Bootlid weatherstrip	1	\$ 389.00
8	Bootlid inner trim	1	\$ 366.00
9	Bootlid RH number plate lamp	1	\$ 78.00
10	Bootlid LH number plate lamp	1	\$ 78.00
11	Rear bumper	1	\$ 1,219.00
12	Rear bumper lower garnish	1	\$ 313.00
13	Rear bumper towing cover	1	\$ 36.00
14	Rear bumper RH corner reverse sensor	1	\$ 257.00
15	Rear bumper RH side reverse sensor	1	\$ 257.00
16	Rear bumper RH centre reverse sensor	1	\$ 257.00
17	Rear bumper LH centre reverse sensor	1	\$ 257.00
18	Rear bumper LH side reverse sensor	1	\$ 257.00
19	Rear bumper LH corner reverse sensor	1	\$ 257.00
20	Rear bumper reverse sensor rubber seal	1	\$ 41.00
21	Rear bumper reverse sensor wire harness	1	\$ 118.00
22	Rear bumper lower trim chrome moulding	1	\$ 421.00
23	Rear bumper RH bracket	1	\$ 56.00
24	Rear bumper LH bracket	1	\$ 56.00
25	Rear bumper RH side holder	1	\$ 43.00
26	Rear bumper LH side holder	1	\$ 43.00
27	Rear bumper centre bracket	1	\$ 116.00
28	Rear bumper RH lower bracket	1	\$ 42.00
29	Rear bumper LH lower bracket	1	\$ 42.00
30	Rear bumper RH exhaust chrome cover	1	\$ 289.00
31	Rear bumper LH exhaust chrome cover	1	\$ 289.00
32	Rear bumper reinforcement	1	\$ 790.00
33	RH taillamp assy	1	\$ 832.00
34	RH taillamp panel	1	\$ 198.00
35	RH taillamp lock clips	1set	\$ 48.00
36	RH taillamp lower bracket	1	\$ 48.00
37	RH headlamp frame sealing	1	\$ 69.00
38	LH taillamp assy	1	\$ 832.00
39	LH taillamp panel	1	\$ 198.00

40	LH taillamp lock clips	1set	\$	48.00	x
41	LH taillamp lower bracket	1	\$	48.00	de
42	LH headlamp frame sealing	1	\$	69.00	x u
43	End panel	1	\$	1,012.00	bt
44	End panel inner garnish	1	\$	184.00	de
45	Rear spare tyre panel	1	\$	1,874.00	x
46	Rear spare tyre panel insulator	1	\$	296.00	x
47	Rear spare tyre top cover board	1	\$	569.00	x
48	Rear windscreen glass with rubber moulding	1	\$	1,372.00	x
49	Rear RH fender	1	\$	2,996.00	x
50	Rear RH fender inner trim	1	\$	684.00	x
51	Rear RH fender splash shield	1	\$	189.00	x
52	Rear LH fender	1	\$	2,996.00	x
53	Rear LH fender inner trim	1	\$	684.00	x
54	Rear LH fender splash shield	1	\$	189.00	x
55	Rear spare tyre top cover board	1	\$	579.00	x
56	Exhaust silencer rubber mountings	1	\$	86.00	de
57	Driver seat belt	1	\$	755.00	x
58	Driver seat belt buckle	1	\$	156.00	x
59	Front LH passenger seat belt	1	\$	755.00	x
60	Front LH passenger seat belt buckle	1	\$	156.00	x
61	Rear RH passenger seat belt	1	\$	755.00	x
62	Rear RH passenger seat belt buckle	1	\$	156.00	x
63	Rear LH passenger seat belt	1	\$	755.00	x
64	Rear LH passenger seat belt buckle	1	\$	156.00	x
65	Rear RH wheel bearing	1	\$	584.00	x
66	Rear LH wheel bearing	1	\$	584.00	x

\$ 29,639.00

Parts less 10% \$ 2,963.90

Total \$ 26,675.10

No.	Special Nett Items	Qty	Amount S\$	
1	Bootlid inner trim clips	1set	\$	80.00
2	Bootlid spoiler	1	\$	1,100.00
3	Rear windscreen glass sealant	1	\$	80.00
4	Rear windscreen glass inner seal	1	\$	60.00
5	Rear RH fender joint sealant	1	\$	100.00
6	Rear RH fender inner trim clips	1set	\$	85.00
7	Rear RH fender splash shield clips	1set	\$	60.00
8	Rear RH fender joint sealant	1	\$	100.00
9	Rear LH fender inner trim clips	1set	\$	85.00
10	Rear LH fender splash shield clips	1set	\$	60.00
11	End panel joint sealant	1	\$	80.00
12	End panel inner garnish clips	1set	\$	70.00
13	Rear number plate	1	\$	80.00
14	Exhaust silencer (after market) → duck price	1	\$	2,800.00
15	Exhaust silencer gasket (after market)	1	\$	78.00
16	Rear RH sport rim	1	\$	1,150.00
17	Rear RH tyre	1	\$	550.00
18	Rear LH sport rim	1	\$	1,150.00

19	Rear LH tyre	1	\$	550.00
		Total:	\$	8,318.00

X 44.

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00
2	Spray painting on affected areas and panels	\$ 1,300.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 80.00
5	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00
6	Remove and replace garnish, trims, seat and boards to assist repair	\$ 360.00
7	Remove and replace exhaust silencer, gasket and rubber mouldings to assist repair	\$ 350.00
8	Conduct diagnose and reset electronic control system	\$ 450.00
9	Remove and replace bootlid inner mechanism to new bootlid	\$ 220.00
10	Remove and replace roof lining, garnish, trims, seat and boards to repair	\$ 550.00
11	Remove and replace front and rear seat belts and buckles to repair	\$ 320.00
12	Conduct diagnose and reset electronic control system	\$ 480.00
13	Test drive and adjust wheel alignment system	\$ 180.00
14	Remove and replace rear wheel bearings to assist repair	\$ 500.00
	Total:	\$ 6,370.00

700

700

30

30

30

60

80

200

60

X 7

X

X 44.

X

X

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Tanfer 97495749
 up 25/11/22 12pm
 15 days after repair
 tanfer 97495749
 06 days
 - To check consistency of accident
 - To check part prices

Spare Parts: \$ 26,675.10
 Special Nett: \$ 8,318.00
 Labour: \$ 6,370.00

Total Amount: \$ 41,363.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: